



METAL SHARK® 2 BD

English **Operator's Manual**

Tectronix Systems Inc., 9 - 18812 96 Ave, Surrey BC, Canada, V4N 3R1
PH: +1 604-607-6028, FAX +1 604-607-6026 www.metal-shark.com

Index

3.	Safety Messages	7
3.1.	Safety Symbols and Definitions	7
3.2.	General Safety Instructions	7
3.3.	Safety Instructions for the Metal Detector	9
3.3.1.	Installation Instructions	9
3.3.2.	Connecting Instructions	9
3.3.3.	Instructions about Operation	9
3.3.4.	Protection against Interference	9
4.	Getting Started	11
5.	Introduction	13
5.1.	General Information	13
5.1.1.	Information about this Manual	13
5.1.2.	Content of this Manual	13
5.1.3.	Target Group for this Manual	13
5.1.4.	Typographic Conventions	14
5.2.	Scope of Application and Qualification	15
5.2.1.	Normal Use	15
5.2.2.	Misuse	15
5.2.3.	Owner's Obligation to Exercise Due Care	15
5.2.4.	Requirements for Operating Staff	16
5.2.5.	Requirements for Service and Maintenance Staff	16
6.	Technical Description	17
6.1.	Method of Operation	17
6.2.	Operating Limits	17
6.3.	Technical Data	18
6.4.	Metal Detector METAL SHARK® 2 BD	19
7.	Transport	21
7.1.	Safety & Protection Instructions	21
7.2.	Lifting	22
8.	Mechanical Installation	23
8.1.	Metal-Free Zone	23
8.2.	Minimum Distance Between Motor and Sensor Head	24
8.3.	Gap Between Sensor Head and Product	24
8.4.	Vibrations	24
8.5.	Feed of Belt Through Sensor Head	25
8.6.	Mounting on Conveyor / Frame	25
8.7.	Keep Conveyor Belt Clean	26
8.8.	Welding of Transversal Struts and Contact Points	26
8.9.	Isolation of Drums and Shafts	27
9.	Electrical Installation	29
9.1.	Terminals of Power Supply Board	30
9.2.	Relay K1, K2 - Function	30
9.3.	Terminals on the Mainboard	31

9.4.	Wiring Diagram Examples.....	32
9.4.1.	Belt Controls STR1 and STL1	32
9.4.2.	Belt Controls STR2 and STL2	33
10.	Control Panel and Main Screens.....	35
10.1.	The Control Panel.....	35
10.2.	The Main Screens.....	36
10.2.1.	The Bar Graph's Screen Elements.....	37
10.2.2.	The 2D Plot's Screen Elements	38
10.2.3.	The Scope's Screen Elements	39
11.	Initial Parameter Setup (all types, except BIG pba).....	41
12.	Daily Operation Overview.....	43
11.	Daily Operation.....	45
11.1.	PRODUCT – Select & Edit Existing Products	45
11.2.	TEST – Check Metal Detector's Performance	46
11.3.	TEACH – Add New Product	47
11.4.	OPTIMIZE – Improve Stability & Sensitivity	51
11.4.1.	Optimize with the Histogram	51
11.4.2.	Optimize with the 2D Plot	53
12.	MENU – Daily Operation Setup.....	57
12.1.	REPORT MENU.....	57
12.1.1.	IFS/HACCP REPORT.....	58
12.1.2.	METAL REPORT.....	59
12.1.3.	EVENT REPORT	59
12.1.4.	METAL COUNTER	59
12.1.5.	TOTAL COUNTER.....	59
12.1.6.	PRINT.....	60
12.1.7.	INTERFACE.....	60
12.1.8.	BAUDRATE RS232.....	60
12.1.9.	SHARKNET UNIT #.....	60
12.1.10.	MAIN SCREEN.....	60
12.1.11.	HISTOGRAM LIMIT %.....	60
12.1.12.	INFO SOFTWARE.....	60
12.2.	TEST MENU.....	61
12.3.	PASSWORD (MENU).....	62
12.4.	PRODUCT MENU.....	63
13.	MENU – General Settings	65
13.1.	PRODUCT MENU	65
13.1.1.	REJECT MENU	65
13.1.2.	TEACH SETUP	67
13.1.3.	ADVANCED (MENU)	68
13.2.	SYSTEM MENU	71
13.2.1.	DATE/TIME MENU	71
13.2.2.	AUTOSPEED MENU	72
13.2.3.	CIP MENU	73
13.2.4.	BRC MENU	74
13.2.5.	IN/OUT MENU.....	74
13.2.6.	FILTER MENU.....	78

13.3.	FACTORY MENU	80
14.	Trouble Shooting.....	81
14.1.	Error Messages	81
14.2.	Reset to Default Values.....	82
14.2.1.	Passwords and Language	82
14.2.2.	Factory Settings	82
14.3.	Problem Solving	83
14.3.1.	Problem: Still Considerable Metal Alarms After TEACH.....	83
14.3.2.	Problem: Still Few Metal Alarms After TEACH.....	83
14.3.3.	Problem: TEACH ends After Short Period of Time	83
14.3.4.	Problem: Poor Metal Sensitivity After TEACH	83
15.	Maintenance and Regular Inspections	85
15.1.	Maintenance	85
15.2.	Regular Inspections	85
15.3.	Notes	85
16.	Annex	87
16.1.	Declarations	87
16.1.1.	CE - Declaration of Conformity.....	87
16.1.2.	Declaration of Manufacturer	88
	Parameter List METAL SHARK® 2 BD/ Software Version 1.10a	89

3. Safety Messages

3.1. Safety Symbols and Definitions

In this manual we use the following safety symbols. These symbols are supposed to draw the readers attention especially to the text next to the safety symbol.



General Danger!

This Symbol indicates that there is a potential danger for life and health.




Danger due to High Voltage!

This symbol indicates that there is a potential danger for health and life due to high voltage. Only qualified electricians are allowed to carry out tasks that are marked with this symbol.



Danger due to Moving Parts!

This symbol indicates that exposed moving parts may injure your fingers or hand.



Caution!

This symbol indicates that there is a potential danger for machinery, material or the environment.

3.2. General Safety Instructions



Danger!

Before working with the metal detector read these safety instructions thoroughly.



Never put the metal detector into operation without the safety devices provided by the manufacturer. Only specially trained maintenance staff is allowed to operate the equipment without the safety devices.



Shut down the machine immediately if the safety devices are not operating properly or if there are other apparent defects which pose a danger. Any defects must be eliminated or reported immediately.



Always observe any warning signs attached to the machine. They help prevent dangerous situations. The removing of these warning signs is strictly prohibited.



Never put the metal detector into operation

- if you have not received complete initial training from the owner,
- if you have not fully read the operating instructions or
- if you have not fully understood the operating instructions.



Not operating the machine correctly may result in severe injury or damage.



Entering the area of the equipment is strictly prohibited for unauthorised persons. An unauthorised person is a person who has not been instructed to work on the metal detector.



Wear closely fitting working clothes which cannot get caught in rotating parts (e.g. conveyor belt).



Keep the floor at your place of work clean. Remove oil and obstructions immediately.



Open flames and smoking are not allowed.



Motor control equipment and electronic controllers are connected to hazardous line voltages.



Never touch any live parts. Electric shocks may lead to severe injury or death.



Disconnect power before checking controllers or performing maintenance, be sure equipment is properly connected to Protective Earth (PE).



During servicing or maintenance work always wear insulated safety shoes with thick crepe soles and safety glasses.



Report any damaged cables to the maintenance staff immediately.



Keep all access doors to the electrical equipment locked.



Do NOT operate the machine without guards in place.



Do NOT touch parts marked with this symbol during machine in operation.

3.3. Safety Instructions for the Metal Detector



Attention!

Smooth and safe running of METAL SHARK® BD Metal Detectors is only possible if the following measures have been taken.

3.3.1. Installation Instructions

Always attach an earth clamp for welding equipment directly next to the weld.

Never allow the welding current to flow through the housing of the metal detector. This would damage the metal detector beyond repair.

3.3.2. Connecting Instructions

- Make sure that the mains voltage is the same as that required for the equipment.
- The detector must be fitted and connected up by trained staff only.
- Observe general installation regulations for setting up and operating electrical equipment (VDE 0100).
- Consequently, never perform any work on the metal detector when it is switched on.
- Take precautions to protect human life and the machine in accordance with the local conditions and regulations.
- The Metal Detector METAL SHARK® 2 BD series is designed for permanent, steady-state installation.
- Never connect or disconnect control cables or coaxial cables whilst the metal detector is switched on.
- Never connect mains cables, control cables or coaxial cables incorrectly.
- Observe maximum operating voltage and the current-carrying capacity of the output contacts.
- Use screened/twisted-wire mains and control cables.
- Never lay the mains cable and control cable together in a single cable run.
- Make sure the metal detector is properly earthen (protective earth - PE).

3.3.3. Instructions about Operation

To prevent Metal Detector METAL SHARK® series from ageing prematurely or being damaged beyond repair, please observe the following instructions:

- The metal detector should always remain switched on. This will maximise the service life of the electronic circuitry.
- Only operate the metal detector under suitable conditions (refer to chapter “3.2.1. Normal Use”).

3.3.4. Protection against Interference










The mains input of the metal detector is protected against interference.

A high level of operational reliability and additional protection against malfunctions is achieved by the following measures:

- Use of mains filters if the mains voltage is affected by the switching-on of heavy-load appliances (compensation systems, welding equipment, HF furnaces, solenoid valves, etc.).
- Providing suppresser circuits for inductance appliances (solenoid valves, contactors, electromagnets) using RC elements (Resistor/Capacitor elements) in order to absorb the energy being released by switching off.

4. Getting Started

Here we provide an overview of the actions you have to take before starting to work with the metal detector METAL SHARK® 2 BD.

1.  Read the safety instructions.
Note: For more information read chapter "1. Safety Messages".
2.  Become familiar with the metal detector.
Note: For more information read chapter "4. Technical Description".
3.  Move the metal detector to the location where you want to install it.
Note: For more information read chapter "5. Transport"
4.  Install the metal detector mechanically.
Note: For more information read chapter "6. Mechanical Installation"
5.  Check the metal detector's electrical installation and connect the mains power.
Note: For more information read chapter "7. Electrical Installation"
6.  Become familiar with the control panel and the main screens.
Note: For more information read chapter "8. Control Panel and Main Screens"
7.  Set up parameters for initial operation.
Note: For more information read chapter "9. Initial Parameter Setup"
8.  Teach products, optimize stability and sensitivity, check the performance and then start your normal production.
Note: For more information read chapter "10. Daily Operation Overview", "11. Daily Operation" and "12. MENU - Daily Operation Setup"
9.  If necessary change further settings of the METAL SHARK® 2.
Note: For more information read chapter "13. MENU - General Settings"

5. Introduction

5.1. General Information

5.1.1. Information about this Manual

Validity:	Metal detector type METAL SHARK® 2 BD BD
Manufacturer:	CASSEL Messtechnik GmbH In der Dehne 10 37127 Dransfeld Germany
Print date of this manual:	27. October 2009

5.1.2. Content of this Manual

This manual contains all general information that is necessary for setting up and running METAL SHARK® 2 BD Metal Detectors.

This manual was compiled in October 2009 according to the guidelines of the European standard EN ISO 12100-1 and EN ISO 12100-2, „Safety of machines“. It completes the existing national regulations for accident prevention that you have to follow when running such machines.

Before the initial operation of the metal detector all persons that are authorised to work on and with the metal detector have to read and understand this manual. Additionally, the employer should provide short information on what to do and not to do with the machine. Special interest is to be paid to the safety instructions.

The manual must stay with the metal detector. All authorised persons must have access to it at any time. You are not allowed to remove any chapters from this manual. A missing manual or missing pages (especially "1. Safety Messages") have to be replaced immediately.

Note: CASSEL Messtechnik GmbH gives no implicit guarantees regarding standard qualities or suitability for a certain application.

This documentation contains information which is subject to copyright. No part of it may be photocopied, duplicated, translated or recorded on data media without prior consent from CASSEL Messtechnik GmbH.

This documentation is not subject to change control by CASSEL Messtechnik GmbH. The manufacturer reserves the right to make changes to this documentation. All rights reserved.

5.1.3. Target Group for this Manual

This document is directed to operators and quality managers as well as company technicians with the following tasks:

- operation of the metal detector,
- regular inspections,
- safety check before and during the work with the metal detector,
- maintenance of the metal detector (company technicians only).

5.1.4. Typographic Conventions

Here the different text formats are explained.

Example	Type
Histogram shows the last 232 signals and what they were about	Important expressions
Press MENU to open the menu. Press ESC to return to the main screen.	Function Keys
Select SYSTEM MENU...	Menu Points
dry : Products with low...	Menu Parameters
BAUDRATE RS232 (A040) sets...	Parameter Code
Note : Do not ...	Hints
Refer to chapter "3.2. <i>Scope of Application and Qualification</i> "	References
...the error message PVS Test Elapsed .	Errors
Danger!	Safety hints

5.2. Scope of Application and Qualification

5.2.1. Normal Use

The Metal Detectors of the METAL SHARK® 2 BD series are solely designed for detecting foreign metal bodies in non-metal products. Metal can be detected in products that are in a

- solid,
- liquid or
- powder

form.

In addition you have to secure that the metal detector is only operated when standing in a stable position.

Note: Refer to chapter “4.3. Technical Data” for more information.

5.2.2. Misuse

The METAL SHARK® 2 BD series is not designed for uses other than those listed in chapter “3.2.1. Normal Use” otherwise it is regarded as misuse. In particular, pay attention to the fact that it is not allowed

- to change or remove safety components from the metal detector or the associated peripheral equipment in order to perform measurements other than those indicated in chapter “3.2.1. Normal Use”,
- to use the machine for a purpose which is not approved,
- to convert the machine without consent from CASSEL Messtechnik GmbH in order to use it for a different purpose. Please bear in mind that if you convert the metal detector you are considered the manufacturer.
- to step on or climb over the machine (especially the conveyor belt),
- to transport humans or any kind of material with the metal detector

5.2.3. Owner’s Obligation to Exercise Due Care

The METAL SHARK® 2 BD series has been designed and built taking due consideration of a hazard analysis and after careful selection of the harmonised standards to be observed, as well as other technical specifications. It is therefore state of the art and guarantees maximum safety.

However, in practical operation this safety can only be maintained if all the necessary measures are taken. As part of his obligation to exercise due care, the owner must take these measures and supervise their implementation.

The owner of the equipment must, in particular, ensure

- that the machine is only subjected to normal use (“3.2.1. Normal Use”),
- that the machine will only be operated if it is in good working condition and the safety devices are checked regularly to make sure they are operative,
- that the Operator’s Manual is always in a legible state and is available in its entirety in a place accessible for all operators at any time,
- that only adequately qualified and authorised staff operates, services and repairs the machine,
- that before working with the metal detector for the first time, and also thereafter on a regular basis, the staff receives instruction on all the relevant issues regarding safety at work and environmental protection and that they are acquainted with the Operating Instructions and particularly the safety instructions therein,
- that all the safety signs and warnings attached to the machine are not removed and remain legible.

5.2.4. Requirements for Operating Staff

To operate the Metal Detector METAL SHARK® 2 BD series no special knowledge of measuring technology, mechanical engineering or electrical engineering is necessary. However, the operating staff must be at least 18 years of age and, before working with the metal detector for the first time, must have received training from the owner of the machine.

After receiving initial training the operating staff must be in a position to perform the following activities without supervision:

- Switching the metal detector on and off.
- Adjusting settings that password level 1 and 2 users are able to set up
- Being acquainted with the functions of the metal detector for daily operation ("*11. Daily Operation*") and being able to carry them out.
- Performing regular performance checks ("*11.2. TEST - Check Metal Detector's Performance*") and visual inspections on the metal detector.
- Inspecting the safety devices before and during operation.
- Eliminating minor malfunctions for which no occupational training in the field of mechanical engineering or electrical engineering is required (e.g. errors 1-7, "*14.1. Error Messages*").

5.2.5. Requirements for Service and Maintenance Staff

To be able to perform maintenance work properly, a period of occupational training in the area of mechanical engineering must have been successfully completed. However, only qualified electricians are allowed to work inside of electrical cabinets. Only trained maintenance staff is allowed to maintain METAL SHARK® 2 BD Metal Detectors.

For service and maintenance work on the metal detector knowledge of the English or German language is absolutely essential.

After initial training the service and maintenance staff must be in a position to perform the following activities without supervision:

- Same as mentioned in "*3.2.4. Requirements for operating staff*".
- Adjusting settings that only password level 3 users are allowed to set up (e.g. System Menu, Advanced settings in the Product Menu, refer to "*13. MENU - General Settings*")
- Locating and eliminating malfunctions ("*14.1. Error Messages*").
- Inspecting the safety devices on a regular basis.
- Putting the metal detector into operation and taking it out of operation.
- Maintaining and repairing the metal detector.

6. Technical Description

6.1. Method of Operation

METAL SHARK® BD Metal Detectors operate on the principle of inductance measurement, which is briefly described below.

The sensor has two coils:

- the transmitter coil and
- the receiver coil.

The pair of coils must be balanced before measuring. They are balanced automatically after switching on the metal detector. This is called „adjustment“.

In the transmitter coil a generator is used to create a flow of electric current. This creates an electromagnetic alternating field (magnetic field) in the sensor.

If a particle of metal now passes through the metal detector — and hence through the magnetic field — the magnetic field of the transmitter coil changes. As a result of the change in the magnetic field an electric voltage is created in the receiver coil. This process is termed „electromagnetic induction“.

The amount of voltage generated (induced) is directly proportional to the magnetic and electrical properties of the metal piece:

- Large metal pieces induce a higher voltage than small metal pieces
- Magnetic metals (e.g. steel) induce a higher voltage than non-magnetic metals (e.g. aluminium)

The voltage thus induced is measured and then processed and analysed by the electronic circuitry.

Since this method of measurement responds to

- electrical conductivity and
- magnetism

all types of metal are detected. However, magnetic metals are detected more reliably than non-magnetic ones. This way of measuring also makes it possible to detect metal particles inside the product or in non-metal packaging.

The examined products are not harmed or changed in any way.

6.2. Operating Limits

Not only metals but also many other materials and raw materials are more or less electrically conductive. The reasons for this can, for example, be that the products consist of

- salts,
- sugar,
- minerals,
- moisture or
- carbons.

This means that a voltage is constantly being induced in the receiver coil although there are no metal particles in the material being examined. This effect is termed „product effect“ or „material effect“.

The product effect has a characteristic value for each material. Since this value is constant within a certain bandwidth, it can be taken into account by the metal detector and compensated.

The level of sensitivity which can be achieved in practice often depends on:

- How well the metal detector compensates the product effect.
- How carefully the metal detector has been installed (e.g. strong vibrations, moving metal directly next to the sensor, electromagnetic interferences etc.).


6.3. Technical Data

Nominal voltage	110 – 240 V, 50 – 60 Hz
Nominal power rating	100 VA
External fuse	min. 10A (slow blow), max. 16A (slow blow)
External wiring	1,5mm ² or AWG 14
Internal fuse	240V / 1 A (slow blow)
Power dissipation	20W typ. / 60 W max.
Overload / overtemp protection	yes
Protection class	IP65
Operating temperature	-10 – +40°C
Storage temperature	-20 – +75°C
Relative humidity	20% – 85% (non condensing)
Operating altitude	2000 m
Dimensions WxHxD in mm	240x345x115 (Type D) or 296x345x115 (Type W)
Weight (controller only)	6 kg

6.4. Metal Detector METAL SHARK® 2 BD

The metal detector METAL SHARK® 2 BD consists of at least two parts:

- **sensor head**,
- **controller** and
- optionally conveyor belt and reject device.



7. Transport

7.1. Safety & Protection Instructions



Danger !


To prevent damage to the machine and hazardous injuries when transporting and installing the machine it is absolutely essential that you keep in mind the following instructions:

- Only qualified personnel considering safety instructions is allowed to transport and install the metal detector.
- The machine may only be lifted using the frame provided.
- To transport the machine only the hoisting and sling gear specified here may be used.
- If the frame of the metal detector has rollers make sure that you only transport it on flat surface
- When selecting suitable hoisting equipment always take the following weights into account: depending on size and type, the metal detector can weigh up to 1,000 kg.
- A third person must secure the transport route.
- The transport routes must be cordoned off and secured so that no unauthorised persons may enter the danger zone.
- Sharp edges may cause injuries.
- Suspended loads may drop. There is a risk of fatal injury – never stay under suspended loads.
- Parts lying unsecured on top of one another may slip and drop.
- Only transport the metal detector after it is disconnected from the power supply.
- Also read chapter “1. Safety Messages”.

7.2. Lifting

Choose suitable hoisting equipment. When choosing hoisting equipment always use padded cables or straps. Chains could lead to damage of the metal detector.

Only lift the metal detector at the frame provided (marked green in figure below)



Caution !

Never lift the entire set of equipment at the sensor head or other parts marked red (see figure below). The heavy weight of the entire set of equipment may cause damage to the sensor head.




8. Mechanical Installation

The following points require special attention during installation:

- Metal-free zone
- Consider a gap between product and sensor head
- Vibration
- Feed of belt through sensor head
- Mounting on conveyor / frame
- Keep conveyor belt clean
- Welding of transversal struts and contact points
- Installation of sensor head


8.1. Metal-Free Zone

A metal-free zone is required in front of and behind the sensor head aperture with a length corresponding to 1.5 times the aperture height.




8.2. Minimum Distance Between Motor and Sensor Head

Between motor and sensor head there must be a minimum distance of 1.5x aperture height. Otherwise the metal detector is affected by the magnetic field of the motor.



8.3. Gap Between Sensor Head and Product

If the product has a strong product effect consider a 40 mm gap (minimum) between sensor head and product for best metal sensitivity.




8.4. Vibrations

- Install the metal detector so that it is exposed to as little vibration as possible in operation.
- Light vibrations do not affect the metal detector.
- However, metal alarm can be triggered by a hard shocks.




8.5. Feed of Belt Through Sensor Head

- The detector is installed in the upper run of a conveyor belt.
- The transport belt is fed through the detector on a nonmetallic guide plate (such as a 16 mm plywood sheet) or tensioned to pass through the detector without contact.
- A minimum clearance of 5 mm must be maintained between the guide plate and the detector.
- The inside of the detector opening may not be touched by the guide plate, belt or fibre mat.



8.6. Mounting on Conveyor / Frame

- Ensure even and stable contact between metal detector and mounting bracket.
- The metal detector must not be subjected to any mechanical stress or tension during the installation and during tightening of the mounting bolts.
- Before installing, scrape off paint from the conveyor or mounting frame around all of the mounting holes for the metal detector. All of the mounting bolts must have good electrical contact to the conveyor or mounting frame.



8.7. Keep Conveyor Belt Clean

The transport belt must be kept absolutely clean. Even small metal particles and contamination could trigger a metal alarm on cycle of the transport belt.

The conveyor must be cleaned of metal swarf and dust before installation. Do not unpack the belt until immediately before installation.

- Do not walk on the conveyor belt without clean protective shoe covers or other protective measures. Visible or invisible shoe prints may contain metal particles.
- Ensure that the belt is well-covered, e.g. with cardboard, before welding or grinding. Hot welding slag or grinding sparks can embed themselves in the surface of the belt.

8.8. Welding of Transversal Struts and Contact Points

Check conveyor drawings and installation constructions:

Are there any designated welding spots on the conveyor or base frame in the range of the metal detector, which must be welded after installation of conveyor and base frame?


Mount these welding points!

Background: The measuring field of the metal detector indicates a very small electrical current (pA) in the metal parts of the conveyor. Slightest electrical changes on conveyor frame (for example: contact resistance at a bolted connection is being changed about 0,1 Ohm) can take effect to the measuring field and a metal alarm can be triggered. Only a welded connection insures in perpetuity a constant ohmic resistance.



Caution!


Always attach the grounding clamp of the welding unit directly next to the welding spot. Do not under any circumstances allow welding current to flow through the metal detector. This will lead to the destruction of the metal detector!



Weld transversal struts here (do not bolt)

8.9. Isolation of Drums and Shafts

All drums and shafts have to be mounted one side isolated, for example using a plastic flange housing or plastic sleeve (refer to figure).



9. Electrical Installation



High Voltage!

Only qualified electricians are allowed to perform work inside of electrical cabinets.




High Voltage!

Hazard of electrical shock. Disconnect incoming power before opening the control box lid.




Use a metric Allen key 4 mm to unscrew the control box lid.



Mainboard

Power Supply Board




Terminals of the Mainboard

Terminals of the Power Supply Board

9.1. Terminals of Power Supply Board

Internal 0VDC +24V DC relay K2 relay K1 Fuse AC 47-63Hz




45 - 47 48 - 50 51 - 53 54 - 56 1A T (slow) L1 N PE PE

Terminal #	Function	Description	
45, 46, 47	Ground	Ground potential for internal power supply	
48, 49, 50	+ 24 V DC OUT	Internal Power supply source 24V/300mA max (total max. 400 mA accumulated at all 24V outputs; inclusive of mainboard outputs)	
Relay K2 51, 52, 53	Error alarm OUT	Closed line, potential free, switching capacity: 230V AC at 5 A max or 30V DC at 5A max	
Relay K1 54, 55, 56	Metal alarm OUT	Closed line, potential free, switching capacity: 230V AC at 5 A max or 30V DC at 5A max	
L1, N, PE	AC Power supply IN	Mains power supply 85 - 250 V AC / 47 - 63 Hz / 100 VA	

9.2. Relay K1, K2 - Function

Terminal #	Function	Relay Status				
		Power OFF	ERROR	NORMAL	METAL	
51 52 53	Relay K2 Error alarm OUT					
54 55 56	Relay K1 Metal alarm OUT					

9.3. Terminals on the Mainboard



Terminal #	Name	Ratings	Function
1	AIN1	0-10V DC	Analogue input, application specific (when METAL SHARK® BIG pba = „Matt height, Board thickness, test stick diameter“)
2, 4, 6, 8	AGND	0V Analogue	Analogue Ground
3	AIN2	0-10V DC	Analogue input, belt speed
5, 7	AOUT1, AOUT2	0-10V DC	Analogue output, application specific
9, 11, 13, 15, 17, 19, 21, 23	IN1 - IN8	24V DC, 10kΩ, 3mA	Logic input, functions refer to chapter "13.2.5. IN/OUT MENU" (Parameters E80 - E115)
10, 12, 14, 16, 18, 20, 22, 24	+24V	24V DC	+24V DC source for logic inputs (total max. 400 mA accumulated at all 24V outputs; inclusive of power supply board outputs)
25, 27, 29, 31, 33, 35, 37, 39	OUT1 - OUT8	24V DC,	Logic output, functions refer to chapter "13.2.5. IN/OUT MENU" (Parameters E120 - E155) (total max. 400 mA accumulated at all 24V outputs; inclusive of power supply board outputs)
26, 28, 30, 32, 34, 36, 38, 40	0V	0V DC	Logic ground for logic outputs
41	TX	-5...+5V digital	RS232 Asynchronous Serial-Data (transmitter) output.
42, 44	GND	0V DC	Ground for RS232
43	RX	-5...+5V digital	RS232 Asynchronous Serial-Data (receiver) input.




Caution!

The sum of all +24 VDC loads must not exceed 400mA, including all loads connected to mainboard (terminals 9 -40) and power supply board (terminals 48-50).

9.4. Wiring Diagram Examples

This chapter shows two typical METAL SHARK® 2 wiring examples with CASSEL conveyor belt controls. The specific wiring diagram for your metal detector is shipped along with the documentation.

9.4.1. Belt Controls STR1 and STL1




Caution!

The sum of all +24 VDC loads must not exceed 400mA, including all loads connected to main-board (terminals 9 -40) and power supply board (terminals 48-50).

10. Control Panel and Main Screens

10.1. The Control Panel

This chapter describes the functions of the control panel's keys and LEDs.




- ① **ERROR !** LED indicates a malfunction (more information: chapter "13.1. Error Messages").
- ② **OK ✓** LED indicates that the metal detector is working properly.
- ③ **✓OK** is displayed when the metal detector is working properly.
STOP is displayed when the conveyor belt is stopped (only when using a conveyor belt)
!MET is displayed in case of a metal alarm.
!ERR is displayed in case of an error.
- ④ **Function Keys:** On the Main Screen the keys are preset to **PRODUCT**, **TEST**, **TEACH**, **OPTIMIZE** and **MENU**. In the menu you can assign shortcuts to the upper four keys by pressing the particular key for two seconds in the desired menu.
- ⑤ **METAL** LED indicates a metal alarm.
- ⑥ **ESC-Key:** Press **ESC** to leave the current menu item or data entry. Keep it pressed to return to the Main Screen.
- ⑦ **Arrow-Keys:** Press **▲▼** to choose the menu items and to change the Main Screen Mode (More information: chapter "8.2. The Main Screens"). When entering names and numbers you select the previous or next character with **◀▶**.
- ⑧ **Plus/Minus-Keys:** Press **+/-** to change parameters and to switch between functions.
- ⑨ **OK-Key:** Press **OK** to confirm a selection or entry.

10.2. The Main Screens

The METAL SHARK® 2 has three graphic screen modes:

- **2D plot** (teach area),
- **bar graphs** (histogram) and
- **scope** (oscilloscope)

Press **▲▼** on the main screen to change the screen mode.




bar graphs (default)

We recommend to use the Bar Graph Screen for daily operation. It indicates how close the signals were to a metal alarm. Moreover, the histogram shows the signals of products and metal alerts that have occurred in the last hours.

For the different screen elements refer to "8.2.1. The Bar Graph's Screen Elements".

Press **▼**




2D plot

We recommend the 2D Plot Screen to look for details of a single product sample.

For the different screen elements refer to "8.2.2. The 2D Plot's Screen Elements".

Press **▼**





scope

We recommend that only technicians use the Scope Screen. It shows in detail the signal of short events. It scales automatically. However, when you press **OPTIMIZE** you can adjust the X-axis, Y-axis and time interval of one grid.


For the different screen elements refer to "8.2.3. The Scope's Screen Elements".

10.2.1. The Bar Graph's Screen Elements




- ① **Name** of the currently chosen product.
- ② **Number** of the currently chosen product.
- ③ **Histogram** shows the last 232 signals and what they were about:
green = Good product in secure range (0 - 80%)
yellow = still good product, but almost identified as metal (80 - 100%)
red = metal alarm (>100%)
- ④ **Bar graph** shows the current signal amplitude as described below:

0 - 80 % = product signal
80 - 100 % = still good product, but almost identified as metal (80 - 100%)
over 100 % = metal alarm
X 145%
Metal threshold (always 100 %)
- ⑤ **Signal strength in %** shows how close the signal comes to a metal alarm.
- ⑥ **Signal amplitude** shows the signal strength in millivolts.
- ⑦ **Phase** shows the direction of the current signal.
- ⑧ **Total** shows the total number products. Only displayed if the conveyor is equipped with a photocell.
- ⑨ **Percent of products with metal.**
- ⑩ **Metal** shows the total number of metal alarms.

10.2.2. The 2D Plot's Screen Elements



- ① **Name** of the currently chosen product.
- ② **Number** of the currently chosen product.
- ③ **Red dots** show measured values that left the teach area. Normally, this happens with contaminated products. In case the products are not contaminated you have to optimize.
- ④ **Product signal dots** show measured value of the product signal.
- ⑤ **Teach area** displays the tolerance range in which the signal is identified as product. All signals outside the teach area are identified as metal.

10.2.3. The Scope's Screen Elements



- ① **Name** of the currently chosen product.
- ② **Number** of the currently chosen product.
- ③ **Red dots** show signal amplitude of the X-channel.
- ④ **Green dots** show signal amplitude of the Y-channel.
- ⑤ **t:** shows the time interval of one grid square.
- ⑥ **X:** indicates the grid spacing of the X-channel in millivolt.
- ⑦ **Y:** indicates the grid spacing of the Y-channel in millivolt.

11. Initial Parameter Setup (all types, except BIG pba)

After the mechanical and electrical installation you have to set up a few parameters. The steps below help you to put the metal detector into first operation.

Note: Step 3, Step 4 and Step 5 are not required if the metal detector is supplied as ready-system, e.g. with pipeline, reject device or conveyor. CASSEL factory sets these parameters for ready-systems.

Switch power supply on

Set **LANGUAGE**.

Note: For more information refer to chapter "13.2. SYSTEM MENU".

Set **SPEED** mm/s.

Note: For more information refer to chapter "13.2. SYSTEM MENU".

Set **IN/OUT MENU**.

Note: For more information refer to chapter "13.2.5. IN/OUT MENU".

Set up **REJECT MENU**.


Note: For more information refer to chapter "13.1.1. REJECT MENU".

TEACH product.

Note: For more information refer to chapter "11.3. TEACH - Add New Product".

12. Daily Operation Overview


This chapter explains what steps you have to take in the daily operation of the metal detector.



11. Daily Operation

You always need these functions in the daily operation of the metal detector.

11.1. PRODUCT – Select & Edit Existing Products

Step	Operation	Screen
1. Return to Main Screen	Press ESC to return to the main screen.	
2. Open product list	<p>Press PRODUCT to open the product list.</p> <p>Press ▲▼ to navigate through the product list.</p> <p>The following functions are available:</p> <hr/> <p>SELECT or OK selects the product marked blue in the screen (in the example you would select CAMEMBER).</p> <hr/> <p>EDIT opens the PRODUCT MENU where you can edit the settings of the respective product. ("12.4. PRODUCT MENU")</p> <hr/> <p>COPY copies the currently selected product, in the example MOZZARELLA, to the selected product memory, here CAMEMBER. Confirm with OK.</p> <hr/> <p>DELETE deletes the selected product memory, in the example CAMEMBER. Confirm with OK.</p>	

11.2. TEST – Check Metal Detector's Performance

Step	Operation	Screen										
1. Return to Main Screen	Press ESC to return to the main screen.											
2. Start TEST	<p>Press TEST to start the PVS Test (Performance Validation System Test).</p> <p>The screen prompts the required test stick size. The help text indicate whether you are to feed the test stick with or without a product sample.</p> <p>ESC aborts the test.</p> <p>Note: Refer to chapter "12.2. TEST MENU" to set up the PVS Test (test stick sizes, etc.).</p>											
3. Feed test sticks through sensor	<p>Feed a test stick of the indicated size through the sensor.</p> <p>Note: Do not feed products through the sensor.</p> <p>The display shows:</p> <table><tr><td>Waiting</td><td>when it is waiting for the relative test stick.</td></tr><tr><td>Passed</td><td>when the correct test stick size has been detected.</td></tr><tr><td>Skipped</td><td>when you have set the size of the relative test stick to zero.</td></tr><tr><td>No Signal</td><td>when the time set for the parameter PVS WINDOW min is up and the metal detector has not detected a test stick.</td></tr><tr><td>Big Signal</td><td>when the signal of the test stick is bigger than the value set for max mV. After 10 seconds it switches back to Waiting and you can try again.</td></tr></table> <p>Repeat the test for every kind of metal configured in the TEST MENU to secure that the metal detector works properly.</p>	Waiting	when it is waiting for the relative test stick.	Passed	when the correct test stick size has been detected.	Skipped	when you have set the size of the relative test stick to zero.	No Signal	when the time set for the parameter PVS WINDOW min is up and the metal detector has not detected a test stick.	Big Signal	when the signal of the test stick is bigger than the value set for max mV. After 10 seconds it switches back to Waiting and you can try again.	
Waiting	when it is waiting for the relative test stick.											
Passed	when the correct test stick size has been detected.											
Skipped	when you have set the size of the relative test stick to zero.											
No Signal	when the time set for the parameter PVS WINDOW min is up and the metal detector has not detected a test stick.											
Big Signal	when the signal of the test stick is bigger than the value set for max mV. After 10 seconds it switches back to Waiting and you can try again.											
4. Test completed	<p>As soon as the METAL SHARK® 2 has detected all test sticks the test is completed and the metal detector switches to normal mode. You can now continue with the normal production process.</p> <p>You can later check the test results in the IFS/HACCP REPORT ("12.1.1. IFS/HACCP REPORT")</p>											




11.3. TEACH – Add New Product

Step	Operation	Screen
1. Return to Main Screen	Press ESC to return to the main screen.	
2. Start teach assistant	Press TEACH to start the teach assistant. Use ▲▼ to navigate through the menu.	
3. Choose PROD-UCT NR.	Go to PRODUCT NR. (D005) . Press +/- to choose the desired product number. Confirm with OK . <i>Note: Product 0 is set to neutral and can not be changed.</i>	
4. Choose PRODUCT NAME	Go to PRODUCT NAME (D010) . Press OK to edit it. Press +/- to change the current letter. Press ◀▶ to select the previous/next letter. <i>Note: You can only use Latin characters.</i> Confirm the name with OK .	



Continued on next page

Step	Operation	Screen
5. Select product characteristics	Go to PRODUCT IS... (D015) . Press OK . Press +/- to choose the characteristic that describes your product:	<div>Set product and press NEXT</div> <div>✓OK MOZZARELLA 5</div> <div>-</div> <div>TEACH Step 1: Set Product</div> <div>-</div> <div>PRODUCT NR. 005</div> <div>PRODUCT NAME MOZZARELLA</div> <div>PRODUCT IS... salty</div> <div>FREQ. SELECT 300000</div> <div>TEACH MODE precise</div> <div>NEXT</div> <div>-</div> <div>EXIT</div> <div>Total 0 25 mV</div> <div>Metal 0 0 % 166.50"</div>
	dry Products with little residual moisture like powder and solid products	
	wet Products with high amount of moisture, but few salt or spice content, e.g. sausages, meat, fruits, vegetables	
	salty Products with high salt content and good conductivity, e.g. cheese	
	frozen Deep frozen products (-18°C/0°F)	
	melting Deep frozen products with lightly melted surface	
	alu foil Products packaged in metal-ized film	
	plastic Plastic granulate with graphite	
	vibration Vibrations in the construction	
	shock Hard knocks and shocks	
optimize All product tolerances are set to x1.0 by default		
neutral no product effect. Run the metal detector without TEACH . Set METAL SENSE mV (D120) only.		
Confirm with OK .		
Continued on next page		

Continued on next page

Step	Operation	Screen
6. Select frequency	<p>Go to FREQ. SELECT (D020). Press OK. Press +/- to select the desired frequency.</p> <p>Single-Frequency-Sensor: This parameter cannot be changed.</p> <p>Dual- or Four-Frequency-Sensor and AUTO FREQUENCY (D115) set to yes: FREQ. SELECT is determined automatically. You cannot change it.</p> <p>Dual- or Four-Frequency-Sensor and AUTO FREQUENCY (D115) set to no: You can choose between the available sensor frequencies (only technicians).</p> <p>Confirm with OK.</p>	 
7. Select TEACH MODE	<p>Go to TEACH MODE (D025). Press OK. Press +/- to select quick or precise:</p> <div style="display: flex; justify-content: space-between;"> <div style="width: 20%;"> <p>quick</p> <p>precise</p> </div> <div style="width: 80%;"> <p>3 to 7 product samples are necessary for the teach process. The product is taught with large tolerance but therefore faster.</p> <p>As a result, the metal detector does not detect with highest metal detection performance. We recommend to optimize the sensitivity afterwards using the OPTIMIZE-function.</p> <p>8 to 14 product samples are necessary for the teach process.</p> <p>The result is that the metal detector is almost optimally adjusted to the product and, therefore, achieves very good results. In most cases you do not have to OPTIMIZE.</p> </div> </div> <p>Confirm with OK.</p>	
8. Check settings and continue	Check your settings. Press NEXT to go to the next teach step.	

Continued on next page

Step	Operation	Screen				
9. Feed products through sensor	<p>Feed product samples through the sensor. The number of products depends on what you have set up for TEACH MODE:</p> <table><tr><td>quick</td><td>3 to 7 product samples</td></tr><tr><td>precise</td><td>8 to 14 product samples</td></tr></table>	quick	3 to 7 product samples	precise	8 to 14 product samples	
quick	3 to 7 product samples					
precise	8 to 14 product samples					
10. Teach successful	<p>As soon as the METAL SHARK® 2 has collected all necessary data a help text confirms that the teach process has been successful.</p> <p>The product is now added to the product list and the metal detector is adjusted to the product.</p>					

11.4. OPTIMIZE – Improve Stability & Sensitivity

Below two ways are described how to optimize the METAL SHARK® 2's sensitivity and stability. Typically, use **OPTIMIZE** after **TEACH** in case the result of the teach assistant is not satisfactory.


Note: For products with **PRODUCT IS...** set to **neutral** refer to "11.4.3. Optimize with **PRODUCT IS...** set to **neutral**".

11.4.1. Optimize with the Histogram

Step	Operation	Screen
1. Return to Main Screen	Press ESC to return to the main screen.	
2. Choose bar graph screen	Press ▲▼ until the bar graph screen is shown. Note: For more information on the 2D plot refer to chapter "8.2.1. The Bar Graph Screen Elements". The main screen example: Products frequently give out metal alarms (red lines). Many products are only within the tolerance range (yellow lines). Press OPTIMIZE if these products are not contaminated.	
3. Set TOL. X and/or TOL. Y	The yellow help text shows that you should change TOL. X and TOL. Y . A value between 60 and 80% is the optimal setting for best sensitivity at highest stability. Press TOL. X or TOL. Y . Press +/- to increase/decrease the value. Confirm with OK . In the example we increase TOL. X and TOL. Y from 1.2 to 1.3. Note: For more information on tolerances refer to "13.1.3. ADVANCED (MENU)"	
4. Check result and adjust	Due to increasing the tolerance the products are not identified as metal anymore. The histogram of the X-value show, however, that the majority of the signals are still within the tolerance range between 80 and 100%. Consequently, "irregular products" may cause metal alarms. Therefore, increase TOL. X , in this example to 1.4.	

Step	Operation	Screen
5. Check result and adjust	<p>Due to increasing TOL. X all signals are in the range below 80%. All histograms are now green. Irregular products do not cause metal alarms. They are within the tolerance range.</p> <p>The metal detector is now set up optimally. Only contaminated products cause metal alarms.</p>	<p>The screenshot shows the operator's interface. At the top, a yellow banner reads 'Set TOL. X to make X max. 80%'. Below this, a green checkmark and 'OK' are displayed next to 'MOZZARELLA' and a large '5'. Two histograms are shown: 'TOL. X 1.4' and 'TOL. Y 1.3'. The first histogram shows a green bar at 79% and a 100% mark. The second histogram shows a green bar at 78% and a 100% mark. At the bottom, a table shows 'EXIT', 'Total', 'Metal', '907', '38', '4 %', '575 mV', and '1.66°'.</p>

11.4.2. Optimize with the 2D Plot





Step	Operation	Screen
1. Return to Main Screen	Press ESC to return to the main screen.	
2. Choose 2D plot screen and press OPTIMIZE	<p>Press ▲▼ until the 2D plot screen is shown.</p> <p>Note: For more information on the 2D plot refer to chapter "8.2.2. The 2D Plot's Screen Elements".</p> <p>In the example an irregular product causes a wrong metal alarm (!MET). Press OPTIMIZE to optimize the teach-area (inside of the green line).</p>	

Step	Operation	Screen
3. Increase tolerance or press FREEZE	<p>Now you have two options: Either you increase the tolerance (as described in the previous chapter) or you can press FREEZE which gives you the following options:</p> <div> <div> <p>Simple Freeze</p> <p>Records product signals over a longer period of time. This way you see how good the teach area describes the product.</p> <p>For more Information refer to "11.4.2.1. Simple Freeze".</p> </div> <div> <p>Add to Teach Area</p> <p>Adds the signals of irregular products to the teach area.</p> <p>For more Information refer to "11.4.2.2. Add to Teach Area".</p> </div> <div> <p>New Teach Area</p> <p>Deletes the old teach area. The products you feed through the sensor create the new teach area. The settings are the same as the original TEACH.</p> <p>For more Information refer to "11.4.2.3. New Teach Area".</p> </div> </div> <p>ZOOM lets you zoom in and out.</p> <div> <p>*A zooms automatically</p> <p>*1 - *40 zooms 1 to 40-fold</p> </div>	

11.4.2.1 Optimize with the 2D Plot – Simple Freeze



Step	Operation	Screen
1. Start Simple Freeze	<p>Press OK to start Simple Freeze Mode.</p> <p>Note: Please read chapter "11.4.2. Optimizing with the Teach Area" first.</p> <p>Simple Freeze displays all product signals since you have started Simple Freeze. It shows how optimally the metal detector is adjusted to your product.</p>	
2. Increase/decrease tolerance	<p>In the example the turquoise dots mark the product signals that were recorded. The red circle is the teach area. The white area between the turquoise dots and the teach area is the tolerance range.</p> <p>During Simple Freeze Mode metal detection is enabled. Product signals that exceed the teach area are marked red and cause metal alarms.</p> <p>To increase the metal detection performance and to detect smaller metal contaminants you decrease the tolerance.</p> <p>Note: If too many irregular products are rejected, as described in 11.4.1, increase the tolerance.</p>	
3. Decrease tolerance	<p>Press TOL. X or TOL. Y</p> <p>Press +/- to make the area smaller/bigger.</p> <p>Confirm with OK.</p> <p>Note: Increase / decrease TOL. X and TOL. Y in small steps (0.1).</p> <p>In the example you see that the teach area wraps itself around the product signals more tightly. The grey lines show the teach area before decreasing the tolerances.</p>	
4. Confirm	<p>Decrease the tolerance until the teach area wraps itself perfectly around the product signals.</p> <p>Note: Keep in mind that the less tolerance range you leave the more often irregular products might cause false metal alarms.</p> <p>Press FREEZE again to stop the Simple Freeze Mode.</p>	

11.4.2.2 Optimize with the 2D Plot – Add to Teach Area

Step	Operation	Screen
1. Start Add to Teach Area	<p>This mode lets you modify and extend an existing teach area. Press + to start Add to Teach Area Mode.</p> <p>Note: Please read "11.4.2. Optimizing with the Teach Area" first.</p>	
2. Feed irregular products	<p>Now add the signals of irregular products to the teach area by feeding these irregular products through the sensor.</p> <p>In the example you see that the original teach area is extended by the measured signals.</p> <p>Note: Metal is not detected during this process. Therefore, FREEZE ends automatically after three minutes.</p>	
3. Con- firm result	<p>Press FREEZE.</p> <p>Press:</p> <ul style="list-style-type: none"> OK to save the new teach area / stop FREEZE, + to collect more irregular product signals or ESC to quit and keep the old teach area. <p>In the example you see that products that would be rejected are now within the teach area and thus in the desired range. They are not rejected anymore.</p> <p>Repeat this process if other irregular products cause metal alarms.</p>	

12. MENU – Daily Operation Setup

Preset and automate the functions for the daily operation of the metal detector.

Step	Operation	Screen
1. Return to Main Screen	Press ESC to return to the main screen.	
2. Open Menu	<p>Press MENU to open the menu.</p> <p>Navigate through the menu and submenus with ▲▼.</p> <p>Open the respective menu with OK.</p> <p>Press ESC at any time to abort your current operation</p> <hr/> <p>✓ Marks menus that you are allowed to enter.</p> <hr/> <p>✗ Marks menus that only users of a higher password level are allowed to enter.</p> <p>When you press OK, however, you are prompted to type in the correct password.</p> <p>Refer to chapter "12.3. PASSWORD (MENU)" for more information.</p> <hr/> <p>In case you do not have the necessary rights to enter the specific menu you are prompted to enter the specific password (refer to illustration). If you want to change passwords refer to chapter "12.3. PASSWORD (MENU)".</p>	 

12.1. REPORT MENU

✓OK	MOZZARELLA	5
PRODUCT	REPORT MENU	✓ Level 2
IFS/HACCP	IFS/HACCP REPORT	
	METAL REPORT	
	EVENT REPORT	
MENU	METAL COUNTER	34
	TOTAL COUNTER	276
	PRINT	one by one
TEST	INTERFACE	RS232
	BAUDRATE RS232	115200
EXIT	Total	276
	Metal	34 12 % 25 mV 154.26°

Use the **REPORT MENU** to monitor the production and to automate data logging.

12.1.1. IFS/HACCP REPORT

The **IFS/HACCP REPORT (A005)** shows detailed information about the production. It consists of three parts that are described below: **SUMMARY**, **METAL**, **EVENTS**.

You can switch between the different types with **+/-**.

With **▲▼** you can scroll up and down.

Press **ESC** to return to the main menu.

Press **OK** to print the **IFS/HACCP REPORT**.

Note: Set the parameter **PRINT** to **report** to set up a printer connected to the RS232 interface. More information "11.1.6. PRINT".

✓OK MOZZARELLA 5				
IFS/HACCP REPORT - SUMMARY				
From date/time:	2008-05-03 08:02:54			
To date/time:	2008-05-05 18:15:21			
Number of PVS tests:	4			
Number of passed PVS tests:	3			
Number of failed PVS tests:	1			
Metal Events:	34			
Product Counter:	276			
Percent Metal:	8			
EXIT	Total	276	25 mV	
	Metal	34	12 %	154.26°

The **SUMMARY** shows the following information:

From date/time:	Indicates when the last report was printed.
To date/time:	Indicates the current time and date.
Number of passed PVS tests:	Indicates the number of PVS test that were completed accordingly.
Number of failed PVS tests:	Indicates the number of PVS test that were not completed accordingly.
Metal Events:	Indicates the number of metal events that have occurred since the last report was printed.
Product Counter:	Indicates the number of products that have gone through the sensor since the last report was printed.
Percent Metal:	Indicates the ratio (%) of contaminated products to the total number of products.

✓OK MOZZARELLA 5				
IFS/HACCP REPORT - METAL				
0034 2008-05-05 17:22:24 P005 245 mV 132.88°				
0033 2008-05-05 15:32:12 P005 225 mV 164.74°				
0032 2008-05-05 11:17:33 P005 211 mV 126.36°				
0031 2008-05-05 10:56:34 P005 214 mV 175.56°				
0030 2008-05-05 08:45:17 P005 227 mV 153.98°				
0029 2008-05-04 19:41:43 P005 275 mV 144.54°				
0028 2008-05-04 19:22:59 P005 264 mV 186.76°				
0027 2008-05-04 13:54:24 P005 199 mV 116.92°				
0026 2008-05-04 11:44:23 P005 278 mV 175.53°				
EXIT	Total	276	25 mV	
	Metal	34	12 %	154.26°

METAL shows detailed information about the specific metal events. Here an example of how to read the list:

0034	number of the metal alarm.
2008-05-05	date the alarm occurred.
17:22:24	time the alarm occurred.
P005	product number.
245 mV	voltage that was measured.
132.88°	phase that was measured.

✓OK MOZZARELLA 5				
IFS/HACCP REPORT - EVENTS				
0001 2008-05-01 08:02:54 [01] System started				
0002 2008-05-01 08:18:52 [10] Teach: Successful				
0003 2008-05-01 08:19:34 [20] PRODUCT IS...=dry				
0004 2008-05-01 08:20:14 [35] BALANCE FACTOR=5				
0005 2008-05-01 08:23:15 [36] Set all products				
0006 2008-05-01 08:42:31 [20] Freeze performed				
0007 2008-05-01 08:43:25 [35] PRODUCT X TOL=1.5				
0008 2008-05-01 08:44:43 [35] PRODUCT Y TOL=1.5				
0009 2008-05-01 08:47:10 [35] PRODUCT Y TOL=1.2				
EXIT	Total	276	25 mV	
	Metal	34	12 %	154.26°

EVENTS shows all events since the last print out (max last 1024 events). Here an example of how to read the list:

0001	number of the event.
2008-05-05	date of the event.
17:22:24	time of the event.
[01]	code for the respective type of event.
System started	Indicates which parameter was changed or what action was taken.

12.1.2. METAL REPORT

METAL REPORT (A010) shows the same information like the **IFS/HACCP REPORT - METAL** plus two additional information. Press **↓** to display these.

With **▲▼** you can scroll up and down.

Press **ESC** to return to the main menu.

Press **OK** to print the **METAL REPORT**.

Note: Set the parameter **PRINT** to **report** to set up a printer connected to the RS232 interface. More information "11.1.6. PRINT".

✓OK	MOZZARELLA	5
METAL REPORT		
0034	P005	245 mV 132.88° 600000 Hz 12%/800%
0033	P005	225 mV 164.74° 600000 Hz 12%/800%
0032	P005	211 mV 126.36° 600000 Hz 12%/800%
0031	P005	214 mV 175.56° 600000 Hz 12%/800%
0030	P005	227 mV 153.98° 600000 Hz 12%/800%
0029	P005	275 mV 144.54° 600000 Hz 12%/800%
0028	P005	264 mV 186.76° 600000 Hz 12%/800%
0027	P005	199 mV 116.92° 600000 Hz 12%/800%
0026	P005	278 mV 175.53° 600000 Hz 12%/800%
EXIT	Total	276 25 mV
	Metal	34 12 % 154.26°

The two additional pieces of information are:

600000 Hz	Sensor frequency for this product.
12%/800%	amplification of X and Y for this product.

12.1.3. EVENT REPORT

EVENT REPORT (A015) shows the same information like the **IFS/HACCP REPORT - EVENTS**. However, the data is not deleted at any time. The last 1024 events are always listed. For more information refer to "12.1.1. IFS/HACCP REPORT".

With **▲▼** you can scroll up and down.

Press **ESC** to return to the main menu.

Press **OK** to print the **EVENT REPORT**.

Note: Set the parameter **PRINT** to **report** to set up a printer connected to the RS232 interface. More information "11.1.6. PRINT".

12.1.4. METAL COUNTER

METAL COUNTER (A020) shows how many products have been contaminated.


Press **OK** and then **+** and **↓** simultaneously to reset the counter to zero.

12.1.5. TOTAL COUNTER

TOTAL COUNTER (A025): In case you have a conveyor belt with a photo cell the number of products is counted and displayed here.

Press **OK** and then **+** and **↓** simultaneously to reset the counter to zero.

12.1.6. PRINT



Default: off

PRINT (A030): Protocol mode of optional printer.

Note: Refer to "12.2.5. IN/OUT MENU" and "7.3. Terminals on the Mainboard" to connect a printer to the METAL SHARK® 2.

off	No output to interface
report	You can print various reports by pressing OK in the report screens.
one by one	Each metal alert and event immediately makes the printer print a message.
SharkDiag	for SHARK DIAGNOSE® software at Windows PC
SharkNet	for SHARKNET® software at Windows PC

12.1.7. INTERFACE

INTERFACE (A035) sets the output for the data. Options are:

RS232	Sends data via RS232
Ethernet	Sends data via optional Ethernet or WLAN to PC

Default: RS232

12.1.8. BAUDRATE RS232

BAUDRATE RS232 (A040) sets the speed of the RS232 interface.

Default: 9600

12.1.9. SHARKNET UNIT

SHARKNET UNIT # (A045) sets the address of the controller when it is part of a SHARKNET®.

Default: 1

12.1.10. MAIN SCREEN

MAIN SCREEN (A050) sets which screen is displayed after you switch on the METAL SHARK® 2. Options are: **2D plot** (teach area), **bar graphs** (histogram), **scope** (oscilloscope).

Default: bar graphs

12.1.11. HISTOGRAM LIMIT %


HISTOGRAM LIMIT % (A055) sets a threshold. Only signals that exceed this threshold are displayed in the histogram.

Default: 20

12.1.12. INFO SOFTWARE

INFO SOFTWARE (A060) shows the current software version installed on the METAL SHARK® 2.

12.2. TEST MENU




Use the **TEST MENU** to adjust the settings of the PVS test, explained in “10.2. TEST – Check Metal Detector’s Performance”.


Note: After changing a parameter you are prompted to choose whether you want to change all products or the currently chosen one. Press **+** and **-** simultaneously to change all products or **OK** to change the currently chosen one.

AUTO PVS TEST (B005)	sets up an automatic reminder reminding you to check the performance of the metal detector. Default: no
PVS FE mm (B010)	set the test stick size of the respective metal that is to be found. Note: If you do not want to test a certain metal set the relative parameter to zero.
PVS NonFE mm (B020)	
PVS SS mm (B030)	Default: depends on application Range: 0 - 99.9 [Millimetres]
PVS FE max % (B015)	set the percentage that is not to be exceeded during the test. If it is exceeded an alarm is given out.
PVS NonFE max % (B025)	Note: If you do not want to test a certain metal set the relative parameter to zero.
PVS SS max % (B035)	Default: depends on application Range: 0 - 9999
PVS FREQ hrs (B040)	sets every how many hours a test is to occur if AUTO PVS TEST is set to yes . Default: 24 Range: 1 - 500
PVS WINDOW min (B045)	Time frame for testing after PVS appeared. Default: 30 Range: 1 - 180
PVS ERROR COUNT (B050)	sets how often you can skip or fail the PVS Test before the error message PVS Test Elapsed is displayed. Default: 3 Range: 1 - 999
PVS COUNT METAL (B055)	If set to no the metal counter does not increase when detecting a test stick. Default: no
PVS USE PRODUCT (B060)	If set to no the user is prompted to feed the test stick without a product sample. Default: no


12.3. PASSWORD (MENU)



Level 1: e.g. for operators



Level 2: e.g. for
production manager
and quality manager



Level 3: e.g. for
company technician

Use the **PASSWORD (MENU)** to set the specific passwords and grant operators different rights. This way you ensure that only qualified personnel has access to key functions.

Below the various parameters are explained:

OPEN LEVELS (C005) Sets which password levels are open without having to enter a specific password.

LEVEL 1 PASSWORD (C010) Sets the password for level 1 users, e.g. production line operators. Level 1 users are allowed to **SELECT** products and **TEST** the metal detector's functionality.

Default: CM0001

LEVEL 2 PASSWORD (C015) Sets the password for level 2 users, e.g. production or quality managers. Level 2 users are allowed to **TEACH** and **OPTIMIZE** products, print reports and set up **TEST**.

Default: CM0002

LEVEL 3 PASSWORD (C020) Sets the password for level 3 users, e.g. company technicians. Level 3 users are allowed to access and alter settings in the **PRODUCT MENU** and **SYSTEM MENU**.

Default: CM0003

LOGOUT (C025) Locks all password levels that are higher than the level set for the parameter **OPEN LEVELS**.
Use this function when you are done with your settings and you want to prevent others from changing any settings.

12.4. PRODUCT MENU

✓OK MOZZARELLA 5	
PRODUCT	PRODUCT MENU ✓ Level 2
IFS/HACCP	PRODUCT NR. 005
MENU	PRODUCT NAME MOZZARELLA
	PRODUCT IS... salty
	FREQ. SELECT 300000
	TEACH MODE precise
	REJECT MENU *
TEST	TEACH SETUP *
	ADVANCED *
EXIT	Total 276 25 mV
	Metal 34 12 % 154.26°

Use the **PRODUCT MENU** to preset all products with the same settings or if you want to change settings of an existing product.

Refer to "10.3. TEACH - Teach New Products" for more information on the parameters.

Note: After changing a parameter you are prompted to choose whether you want to change all products or the currently chosen one. Press **+** and **-** simultaneously to change all products or **OK** to change the currently chosen one.

Only level 3 users can access the **REJECT MENU**, **TEACH SETUP** and **ADVANCED**. They are explained in detail in the next chapter.

13. MENU – General Settings

These settings adapt the METAL SHARK® 2 controller to hardware like pusher, conveyor, sensor head etc.

13.1. PRODUCT MENU

13.1.1. REJECT MENU

✓OK	MOZZARELLA	5
PRODUCT	REJECT MENU	✓ Level 3
IFS/HACCP	DELAY mm	0
MENU	DURATION ms	500
TEST	METAL CONTACT	pulse
EXIT	PUSHER TOL mm	100
	METAL-PHOTO mm	0
	BELT STOP PUSH	yes
	Total	276
	Metal	34 12 % 25 mV 154.26°

The **REJECT MENU** sets up the timing for reject devices and photo cell triggering.

DELAY mm (D035)

Delays the metal output signal for a certain distance. Use this to setup the proper reject timing.

The metal detector calculates a time delay based on **DELAY mm** and **SPEED mm/s**.

Note: During the delay period other metal signals which occur are stored in a shift register and are not lost.

Default: 0 [Millimetres]

Range: 0 - 30,000 [Millimetres]

DURATION ms (D040)

is the length of time in milliseconds for which the Metal signal relay remains switched.

Sets the length of a metal output pulse signal. E.g. use this to setup how long a reject signal remains active.

Note: Whilst the relay is switched on, other metal signals which occur are stored in a shift register and are not lost.

Default: 500 [Milliseconds]

Range: 150 - 30,000 [Milliseconds]

	programs the function of the metal alarm outputs.
METAL CONTACT (D045)	pulse Metal alarm as a pulse with the duration DURATION ms . Use e.g. when pneumatic nozzles separate the metal
	gf1 Drives reject flaps with gravity feed applications. Error = flap in reject - position
	gf2 Drives reject flaps with gravity feed applications. Error = flap in ok - position
	mesep Metal separator model MESEP® SE
	inline Security drive of inline reject EX-PWC
	hold Standard value for belt stop with reset push button.
	push1 Pusher with photo cell active 0V (synchronized reject signal).
	push2 Pusher with photo cell active 24V (synchronized reject signal).
	push3 Pusher without photo cell synchronization
	Default: pulse
PUSHER TOL mm (D050)	Tolerance for photo eye trigger. Preset by CASSEL. Default: 30 [Millimetres] Range: 0 - 999 [Millimetres]
METAL-PHOTO mm (D055)	sets the distance between metal detection and photo cell. Default: depends on application Range: 0 - 200 [Millimetres]
BELT STOP PUSH (D060)	yes: The conveyor stops when the pusher is activated. Default: depends on application

13.1.2. TEACH SETUP

MOZZARELLA 5	
PRODUCT	TEACH SETUP ✓ Level 3
IFS/HACCP	SENSE MIN mV 10
MENU	TEACH SENSE mV 25
	QUICK COUNT 3
	PRECISE COUNT 10
TEST	TEACH TIME s 15
	TEACH EXTERN yes
	TEACH REJECT no
EXIT	REMOTE PRODUCT no
	Total 276 25 mV
	Metal 34 12 % 154.26°

In the **TEACH SETUP** you adjust the settings for the teach assistant. For more information refer to chapter "11.3. TEACH - Add New Product".

SENSE MIN mV (D065)

Defines the smallest possible sensitivity that the teach assistant can automatically set. For most cases setup according suggestion of yellow help line.

Note: Use product 0 when setting up this parameter

Range: 3 - 2,000

TEACH SENSE mV (D070)

blanks out signals that are smaller than this value. **TEACH SENSE mV** prevents the metal detector from recognizing e.g. noises as products. It should be at least the value of **SENSE MIN mV**. Signals that are bigger are identified as products. Set this parameter as the yellow help text indicates.

Range: 3 - 2,000

QUICK COUNT (D075)

defines the maximum number of product samples required for TEACH STEP 2 if **TEACH MODE** is set to **quick**.

Default: 3

PRECISE COUNT (D080)

defines the maximum number of product samples required for TEACH STEP 2 if **TEACH MODE** is set to **precise**.

Default: 7

TEACH TIME s (D085)

The teach assistant stops after **TEACH TIME s** is elapsed. You have to feed at least one product sample during that time. In case you do not feed a product the teach assistant stops and sets the highest possible sensitivity.

VERY IMPORTANT: **TEACH TIME s** must be high enough to get at least one product signal. Otherwise the compensation fails!

Recommendations:

Product speed 100-200 mm/sec. → **TEACH TIME s** = 45

Product speed 200-300 mm/sec. → **TEACH TIME s** = 30

Product speed 300-500 mm/sec. → **TEACH TIME s** = 20

Product speed above 500 mm/sec. → **TEACH TIME s** = 15

Default: depends on application

Range: 2 - 300 [Seconds]

TEACH EXTERN (D090)

yes: teach assistant starts when a 24V PLC signal is provided to the appropriate input.

Default: no


TEACH REJECT (D095)

yes: activates metal alarm during teach assistant.

Default: no

REMOTE PRODUCT (D100)	<p>yes: sets PRODUCT 0 – 20 remotely according input voltage 0-10V at terminal AIN1..</p> <p>Note: Refer to Service Manual for detailed information.</p> <p><i>Note:</i> Available only for conveyors supplied by CASSEL</p>
	Default: no
AUTOMATIC TEACH (D105)	<p>yes: only one product sample is required for the teach process. The conveyor belt goes back and forth feeding the product through the sensor automatically.</p> <p>Note: Make sure that CONV. LENGTH mm is set up correctly.</p>
	Default: no
CONV. LENGTH mm (D110)	<p>sets the length of the conveyor belt for AUTOMATIC TEACH.</p> <p>Default: 1,000 [Millimetres], should be set to actual value</p> <p>Range: 100 - 9,999 [Millimetres]</p>
AUTO FREQUENCY (D115)	<p>yes: In case of a two or four frequency sensor head the teach assistant chooses automatically the best frequency automatically.</p> <p>Default: no</p>
TEACH PHOTO mm (D117)	<p>sets the distance from photo cell to sensor end.</p> <p>Default: 999 [Millimetres], should be set to actual value</p> <p>Range: 0 - 999 [Millimetres]</p>

13.1.3. ADVANCED (MENU)




The **ADVANCED (MENU)** is for experts only. Product parameters are automatically set during the teach assistant. This menu allows to modify the product parameters manually.

METAL SENSE mV (D120)	<p>sets the metal sensitivity and thus the threshold for metal detection. If set to 3000 mV metal detection for this product is deactivated and NOT ACTIVE is displayed.</p> <p>To determine which mV a particular metal object generates, refer to mV value in the lower right corner of the display. Bear in mind that non-spherical metal parts may generate different magnitudes depending on their orientation. Magnetic metal parts produce a larger signal than non-magnetic metal parts.</p> <p>Note: Normally, you only have to set METAL SENSE mV for neutral products (PRODUCT IS... = neutral). The teach assistant presets METAL SENSE mV for all other products automatically.</p> <p>Default: set during TEACH</p> <p>Range: 3 - 3,000</p>
--------------------------	--

adds a tolerance range around the product effect. The tolerance range prevents false alarms from irregular products. Increasing **PRODUCT X TOL.** increases the teach area at the X-axis.

PRODUCT X TOL. is automatically added as a factor to the result of the teach assistant. It is not altered by the teach assistant. Thus, it allows to preset a larger tolerance range than the teach assistant automatically considers.

PRODUCT X TOL. (D125)




Default: 1.0

Range: 0.0 - 9.9

adds a tolerance range around the product effect. The tolerance range prevents false alarms from irregular products. Increasing **PRODUCT Y TOL.** increases the teach area at the Y-axis.

PRODUCT Y TOL. is automatically added as a factor to the result of the teach assistant. It is not altered by the teach assistant. Thus, it allows to preset a larger tolerance range than the teach assistant automatically considers.

PRODUCT Y TOL. (D130)



Default: 1.0

Range: 0.0 - 9.9

Hardware amplification factor for the product effect (X channel). The larger the product effect is, the smaller the **AMPLIFICATION X** value has to be. **3%** is the smallest hardware amplification.

AMPLIFICATION X (D135)

When using product memories 1 - 120: **AMPLIFICATION X** is set automatically during teach process according to the following rule:

Very strong product effect amplitude = **AMPLIFICATION X 3%**


Low product effect amplitude = **AMPLIFICATION X 200%**

Default: set during teach process

Values: **3%, 6%, 12%, 25%, 50%, 100%** and **200%**

AMPLIFICATION Y (D140)	Refer to AMPLIFICATION X .
ATTENUATION (D145)	<p>attenuates the signal received from the sensor head.</p> <p>Default: 1/1</p> <p>Values: 1/1, 1/3, 1/10</p>
PHASE (D150)	<p>The setting of the product phase helps to blank out any product effect. It is set automatically during the TEACH process.</p> <p>Note: PHASE is only available with product 1 - 120, not with <i>PRODUCT 000</i>.</p> <p>Default: 0.00°</p>
PHASE TRACK (D155)	<p>adjusts the product's phase during normal operation to compensate slow changes of the product effect phase. The product effect phase may change depending on product temperature and composition.</p> <p>The parameter PHASE TRACK indicates the increment with that the phase is adjusted: The higher this value the stronger the phase tracking. E.g. a 0.10° means 0.10 degree tracking with each product or metal signal.</p> <p>Default: 0.00°</p> <p>Range: 0.00 - 10.00°</p>

13.2. SYSTEM MENU



The **SYSTEM MENU** sets general and basic settings.

Note: Most parameters here are factory preset. Only adjust **SPEED mm/s** and **LANGUAGE**, unless you need to adapt the metal detector to any special requirements.

SPEED mm/s (E005)

For optimum signal evaluation the unit has to be adjusted to the velocity at which the products are passed through the sensor. A correct **SPEED mm/s** setting is absolutely essential.

SHARK® BD: Adjust the setting to the belt speed at which material is passed through the metal detector.

SHARK® BD supplied with conveyor HQ: **SPEED mm/s** is set automatically.

SHARK® GF, SHARK® GF compact: 2000 mm/sec recommended.

OTHERS: Set **SPEED mm/s** at which material is currently passed through the detector.


Range: **100 - 9,999 [Millimetres per Second]**

IMPORTANT NOTE: A correct calibration of the conveyor belt (with ± 2 m/min exactness) is absolutely essential. Otherwise lower metal detection sensitivity is the result!

LANGUAGE (E010)


sets the language of the display texts.

13.2.1. DATE/TIME MENU



Date and time are used in the various reports of the **REPORT MENU**. Adjustable parameters are: **SET DATE (E015)** and **SET TIME (E020)**.

13.2.2. AUTOSPEED MENU


**Caution!**

Only use the **AUTOSPEED MENU** if you know that a 0-10V or 4 - 20 mA speed signal is connected to the AIN2 (input terminal #3).

The speed signal at AIN2 must be calibrated. The calibration defines which speed corresponds to how many millivolts.

Two values must be calibrated:

- The voltage in mV at AIN2 (input terminal #3) that corresponds to a belt speed of 0 mm/sec. (=belt stop);
- The voltage in mV at AIN2 (input terminal #3) that corresponds to a belt speed of **CAL SPEED mm/s**.

**AUTOSPEED (E025)**

yes activates automatic setting of **SPEED mm/s**.

Set calibration voltage for belt speed = 0 mm/s (belt stop).

BELT STOP mV (E030)

Hint: The yellow help text shows the current input signal at AIN2.

Default: 0

Range: 0 - 9,990

CAL SPEED mm/s (E035)

Enter a conveyor speed for the second setpoint.

Recommended setting is 50% of maximum belt speed.

Note: Measure the current speed with a tachometer.

Default: 0

Range: 0 - 9,990

Set calibration voltage for belt speed **CAL SPEED mm/s**.

CAL SPEED mV (E040)

Hint: The yellow help text shows the current input signal.


Default: 0

Range: 0 - 9,990

SPEED mm/s (E005)

shows **SPEED mm/s** as calculated from input AIN2. For information only.

13.2.3. CIP MENU




The **CIP MENU** (CIP = Clean In Place) is for pipeline models only (METAL SHARK® IN LIQUID).

If activated, the reject device toggles between positions "NORMAL" (production) and "REJECT" as long as the CIP input is in state HIGH. Cleaning fluid running through the product pipes cleans all interior surfaces of the reject device.

CIP Reject s (E045)	sets the time for how long the reject device is switched to position "REJECT" (in seconds). Default: 0 Range: 0 - 320 [Seconds]
CIP Normal s (E050)	sets the time for how long the reject device is switched to position "NORMAL" (in seconds) Default: 0 Range: 0 - 999 [Seconds]
CIP Timeout min (E055)	sets the maximum time the detector is in CIP-mode (in minutes). After this time, the detector will switch to normal operation even if CIP input remains HIGH. Next CIP can be activated only after CIP input has been reset to low. Note: Refer to parameter start cip in chapter "13.2.5. IN/OUT MENU". Default: 1 Range: 0 - 999 [Minutes]

13.2.4. BRC MENU



The **BRC MENU** allows you to configure the metal detector in order to comply with the British Retail Consortium (BRC) Food Technical Standard.

REJECT CONFIRM (E060)

yes enables reject monitoring (using optional photo eyes). It thus checks whether the contaminated product was indeed rejected.

Status of the metal detector will switch to "ERROR" if reject device fails.

Note: Refer to parameter **reject valid** in chapter "13.2.5. IN/OUT MENU".

Default: no

BIN FULL (E065)

yes enables reject bin monitoring (with optional photo eye). It thus checks whether the rejection bin is full.

Note: Refer to parameter **bin full** in chapter "13.2.5. IN/OUT MENU".

Default: no

LOW AIR (E070)


yes enables air pressure monitoring (with optional pressure sensor).

Status of the metal detector will switch to "ERROR" (i.e. relay K2 "OFF") if the air pressure is too low.

Note: Refer to parameter **low air** in chapter "13.2.5. IN/OUT MENU".


Default: no

13.2.5. IN/OUT MENU



Setup of the input and output switching lines of the metal detector. Set up the parameters according to the devices connected to IN1 - IN8 and OUT1 - OUT 8 terminals on the mainboard.

Note: For more information refer to "7.3. Terminals on the Mainboard".




Terminals on SHARK mainboard corresponding to **INPUT LINE 1 - INPUT LINE 8**:

INPUT LINE 1 = Terminal 9	INPUT LINE 3 = Terminal 13	INPUT LINE 5 = Terminal 17	INPUT LINE 7 = Terminal 21
INPUT LINE 2 = Terminal 11	INPUT LINE 4 = Terminal 15	INPUT LINE 6 = Terminal 19	INPUT LINE 8 = Terminal 23

Functions of **INPUT LINE 1 - INPUT LINE 8 (E080 - E115)**:

met/err reset	HIGH: Return to normal operation mode after METAL or ERROR
conveyor on/off	Belt control push button input (START / STOP / RESET)
start teach	HIGH: Start TEACH
reject test	HIGH: Trigger reject device now.
reject valid	Connect feedback signal from reject device. ERROR if no signal transition after METAL OUT
reject sync	Photo eye, triggers pusher to product centre
reject safety	LOW: Reject device is locked in position NORMAL, e.g. during cleaning.
keypad lock	HIGH: Keyboard is locked, no data entry possible. Typical application: Key switch.
low air	Monitors compressed air. LOW for more than 30sec.: Triggers Error 7: Low Air (refer to "14.1. Error Messages").
start cip	HIGH: Activates CIP mode (refer to "13.2.3. CIP MENU")
bin full	Monitors reject bin. HIGH for more than 30 sec.: Triggers Error 6: Bin Full (refer to "14.1. Error Messages")
met count reset	HIGH: Resets METAL COUNTER (A020)
false trip	HIGH: Sends a false alarm message to the SHARKNET® software
product 120	HIGH: PRODUCT NR. (D005) is set to 120. LOW: PRODUCT NR. (D005) is set to original number.
met/err key	HIGH: Return to normal operation mode after METAL or ERROR (only available with option: key switch)
booster ok	Monitors booster. LOW triggers Error 17: Booster Error (refer to "14.1. Error Messages") Note: Only change this input when advised by CASSEL.
belt splice	HIGH: Sets sensitivity to SPLICE SENSE mV (E270) LOW: Sets sensitivity to METAL SENSE mV (D120)
product LS	Photo eye signals product's edges during TEACH Step 2: Learning

test no reject	<p>HIGH: activates metal test mode (only with option: key switch).</p> <p>During test mode the conveyer is immediately stopped when metal is detected (output 'error CW') - however, the metal alarm is neither counted nor entered in the event report.</p> <p>Timeout of the test mode is controlled by CIP Timeout min - after this time has elapsed normal metal detection continues. While the test mode is active TEST is displayed.</p>
input off	Input is not active.




Terminals on SHARK mainboard corresponding to **OUTPUT LINE 1 - OUTPUT LINE 8**:

OUTPUT LINE 1 = Terminal 25	OUTPUT LINE 3 = Terminal 29	OUTPUT LINE 5 = Terminal 33	OUTPUT LINE 7 = Terminal 37
OUTPUT LINE 2 = Terminal 27	OUTPUT LINE 4 = Terminal 31	OUTPUT LINE 6 = Terminal 35	OUTPUT LINE 8 = Terminal 39

Functions of **OUTPUT LINE 1 - OUTPUT LINE 8 (E120 - E155)**:

metal	HIGH if metal detected, refer to "13.1.5. REJECT MENU" for details
metal inverse	LOW if metal detected.
error	HIGH during normal operation, LOW if detector is not in normal operation
error inverse	LOW during normal operation, HIGH if detector is not in normal operation
met+err	HIGH if metal alarm or unit not in normal operation, LOW during normal operation
met+err inv.	LOW if metal alarm or unit not in normal operation, HIGH during normal operation
metal zero del	HIGH if metal detected, no DELAY mm (refer to "13.1.1. REJECT MENU")
pv test	HIGH if last sensitivity test more than PV FREQ HOURS ago (refer to "11.2. TEST - Check Metal Detector's Performance")
dual freq	For dual frequency detectors only.
teach confirm	HIGH if TEACH ended successfully ("TEACH Successfull" displayed)
cip out	HIGH if detector is in CIP mode (refer to "13.2.3. CIP MENU" for details)
start conveyor	HIGH if conveyor on/off received a start signal
pusher	The outputs metal and pusher switch to active at the same time: However, pusher switches back to inactive already after 1/3 of the time of DURATION ms (but at least 40 ms). This way a pneumatic pusher is able to return to normal position during DURATION ms .
big metal	HIGH if big metal piece is detected - only BIG pba.
booster on	HIGH switches booster on
conv. forward	Internal function, not for common use
conv. reverse	Internal function, not for common use
metal CW	HIGH: if metal detected LOW: automatically after 140 ms.
error CW	HIGH: like 'error'. When metal test mode is activated via key switch, also when metal is detected. This way the conveyor of the checkweigher stops when metal is detected during test mode.
output off	Output not active. Output remains LOW.

13.2.6. FILTER MENU



The **FILTER MENU** sets filters to improve the detection reliability and suppress noise.

To set VIBRATION mV:

1. Set PRODUCT 000, AMP X% 100, AMP Y% 100
2. Run the production line or the conveyor, but without products and without metal.
3. Read out the peak mV level.
4. Set **VIBRATION mV** to the maximum peak mV level plus 30%.

Default: 10

Range: 3 - 2,000

**VIBRATION mV
(E160)**

blanks out mechanical vibrations of the sensor head.

yes activates vibration filter.

The value of **VIBRATION mV** (above) controls the filter strength:

VIBRATION mV increased: Better suppression of vibration noise, lower detection sensitivity.

VIBRATION mV decreased: Less suppression of vibration noise, better detection sensitivity.

Default: no

**VIBRATION
FILTER (E165)**

Note: Only change this filter when advised by CASSEL.

**BP FILTER
(E170)**

no filter = filter is deactivated. Do not use unless clearly instructed by CASSEL

FFT = special Filter mode. Do not use unless clearly instructed by CASSEL

CCF = default

Default: CCF

**LP FILTER
(E175)**

yes = Lowpass filter activated.

Default: yes

yes enables fast metal detection. Gives a wide speed range. (for GF or fast applications)

**GF MODE
(E180)**

no = normal applications

Default: no (conveyor applications with defined belt speed)

yes (applications with undefined speed)

yes (all gravity feed applications)

13.3. FACTORY MENU


PRODUCT	FACTORY MENU	✓ Level 4
IFS/HACCP	SENSOR CALIB.	✓
	UTILITIES	✓
MENU		
TEST		
EXIT	Total 276 Metal 34 12 %	25 mV 154.26°

The **FACTORY MENU** adopts the electronic cards to the sensor head.

Note: Never touch these parameters. All parameters here are factory preset. Therefore, Password Level 4 is required to change settings in the menu. Level 3 users can enter the menu and read the parameters.

14. Trouble Shooting

14.1. Error Messages



In case of an error:

- the Error-LED lights up,
- the screen indicates **!ERR**,
- an error message is displayed.

Note: Please write down the number of the error and talk to the company technician or call a service technician of CASSEL Messtechnik.

Error #	Error Text	Cause	Remedy	Confirmation
Error 1:	Comp. Pre	<ul style="list-style-type: none"> • Sensor out of the alignment. • Mainboard damaged. • Big metal object in the detector. 	<ul style="list-style-type: none"> • Remove big metal object in the detector • Contact technician 	<ul style="list-style-type: none"> • Turn on/off metal detector
Error 2:	Comp. Fine	<ul style="list-style-type: none"> • Mainboard damaged. 	<ul style="list-style-type: none"> • Contact technician 	<ul style="list-style-type: none"> • Turn on/off metal detector
Error 3:	Signal Clip	<ul style="list-style-type: none"> • Signal permanently too high for one minute. 	<ul style="list-style-type: none"> • Use other products • Contact technician 	<ul style="list-style-type: none"> • Confirm with OK • Restart teach process
Error 4:	Reject	<ul style="list-style-type: none"> • Reject device has been triggered but the reject sensor did not detect the rejection. 	<ul style="list-style-type: none"> • Confirm with OK and repeat test • Contact technician 	<ul style="list-style-type: none"> • Confirm with OK
Error 5:	PVS Test Elapsed	<ul style="list-style-type: none"> • Performance validation test not done within preset period of time. 	<ul style="list-style-type: none"> • Confirm with OK and repeat test 	<ul style="list-style-type: none"> • Confirm with OK • Error reappears, if period of time has expired and the PV test was unsuccessful
Error 6:	Bin Full	<ul style="list-style-type: none"> • The bin is full or a product blocks the sensor. 	<ul style="list-style-type: none"> • Empty bin • Contact technician 	<ul style="list-style-type: none"> • Confirm with OK • Error message reappears after 30 seconds, if bin still full
Error 7:	Low Air	<ul style="list-style-type: none"> • Air pressure monitor signals low pressure. 	<ul style="list-style-type: none"> • Check air pressure supply • Contact technician 	<ul style="list-style-type: none"> • Confirm with OK • Error message reappears after 30 seconds, if not enough air pressure

Error #	Error Text	Cause	Remedy	Confirmation
Error 9:	Keyboard	<ul style="list-style-type: none"> Key is jammed or keyboard connector is loose. 	<ul style="list-style-type: none"> Contact technician 	<ul style="list-style-type: none"> Confirm with OK Error message appears until keyboard is replaced
Error 10:	Memory	<ul style="list-style-type: none"> Memory problem, parameters can not be saved 	<ul style="list-style-type: none"> Turn on/off metal detector Contact technician 	<ul style="list-style-type: none"> Confirm with OK Error message appears until memory is replaced
Error 12:	Check Belt	<ul style="list-style-type: none"> Conveyor belt should run but does not. 	<ul style="list-style-type: none"> Contact technician 	<ul style="list-style-type: none"> Push Start belt button
Error 13:	Output Wiring	<ul style="list-style-type: none"> Overload protection for outputs is triggered. 	<ul style="list-style-type: none"> Contact technician 	<ul style="list-style-type: none"> Turn on/off metal detector
Error 14:	Receiver Clipping	<ul style="list-style-type: none"> Receiver receives a signal that is too large. 	<ul style="list-style-type: none"> Contact technician 	<ul style="list-style-type: none"> Turn on/off metal detector
Error 15:	Sender Clipping	<ul style="list-style-type: none"> Transmitter is overloaded. 	<ul style="list-style-type: none"> Contact technician 	<ul style="list-style-type: none"> Turn on/off metal detector
Error 16:	Transmitter Fault	<ul style="list-style-type: none"> External transmitter amplifier signals fault (e.g. SPD) 	<ul style="list-style-type: none"> Contact technician 	<ul style="list-style-type: none"> Confirm with OK
Error 17:	Sender Power	<ul style="list-style-type: none"> Error in external amplifier 	<ul style="list-style-type: none"> Contact technician 	<ul style="list-style-type: none"> Confirm with OK Turn on/off metal detector
Error 18:	Mat Height Input	<ul style="list-style-type: none"> Physical connection erroneous 	<ul style="list-style-type: none"> Check cable connection 	<ul style="list-style-type: none"> Confirm with OK Turn on/off metal detector
Error 19:	Autospeed Input	<ul style="list-style-type: none"> Physical connection erroneous 	<ul style="list-style-type: none"> Check cable connection 	<ul style="list-style-type: none"> Confirm with OK Turn on/off metal detector

14.2. Reset to Default Values

14.2.1. Passwords and Language

Press **OK**, **ESC** and **F5** for 1.5 seconds during start up (SHARK logo is displayed) to reset all passwords to the default values (CM0001 - CM0003). Also **LANGUAGE** is set to **English**.

14.2.2. Factory Settings

Press **OK**, **ESC** and **F1** for 1.5 seconds during start up (SHARK logo is displayed) to reset all parameters to the default settings preset by the factory.

14.3. Problem Solving

14.3.1. Problem: Still Considerable Metal Alarms After TEACH

Solution:

1. **TEACH** again. If metal alarms occur again:
2. Switch main screen to **2D plot** (refer to "8.2. The Main Screens")
3. **OPTIMIZE** (refer to "11.4. OPTIMIZE – Improve Stability & Sensitivity")
4. **FREEZE** (refer to "11.4.2. Optimizing with the 2D Plot")
5. **Add to Teach Area (+)** (refer to "11.4.2.2. Add to Teach Area")

14.3.2. Problem: Still Few Metal Alarms After TEACH

Solution:

1. **TEACH** again. If metal alarms occur again:
2. Switch main screen to **bar graphs** (refer to "8.2. The Main Screens")
3. **OPTIMIZE** (refer to "11.4. OPTIMIZE – Improve Stability & Sensitivity")
4. Adjust **TOL. X** and **TOL. Y** until signal of normal products = below 80% (refer to "11.4.1. Optimizing with the Histogram")

14.3.3. Problem: TEACH ends After Short Period of Time

Problem: **TEACH** ends after short period of time although no products have been fed through sensor

Solution: Increase **TEACH SENSE mV (D070)** (refer to "13.1.2. TEACH SETUP")

14.3.4. Problem: Poor Metal Sensitivity After TEACH

Solution:

1. Is **SPEED mm/s (E005)** set up correctly? (refer to "13.2. SYSTEM MENU")
2. **TEACH** again. If problem still occurs:
3. Switch main screen to **bar graphs** (refer to "8.2. The Main Screens")
4. **OPTIMIZE** (refer to "11.4. OPTIMIZE – Improve Stability & Sensitivity")
5. Does the display show below 60% when the product is fed through the sensor? (refer to "8.2. The Main Screens")
6. Adjust **TOL. X** and **TOL. Y** until signal of normal products = between 60 and 80% (refer to "11.4.1. Optimizing with the Histogram")

15. Maintenance and Regular Inspections

15.1. Maintenance

The metal detector is a sensitive measuring device which serves to protect other machinery from damage, thus preventing expensive, unscheduled interruptions of production. This manual describes how to install, operate and adjust the sensitivity. The conveyor belt upon which the metal detector is mounted is designed to ensure that the detector works accurately. The metal detector will generally work safely and reliably without having to make additional adjustments after the initial commissioning.

15.2. Regular Inspections

Regular tests of the metal detector's functions are very important to ensure safe operations. The detector must be tested at least on a weekly basis. Additionally, it has to be tested after each maintenance stop or after works have been performed near the detector. If the detector does not function appropriately eliminate the malfunctions immediately; if not, machines protected by the detector must be stopped.

It is recommended to regularly test the metal detector with standardised test objects and to keep records of these tests in a log book. Metal testing spheres are generally supplied with the detector.

A suitable metal testing object and a testing schedule should be established for the examination:

- The testing object should be a sphere of the smallest diameter which detection is required. The sphere can be glued to a piece of plastic or may be cast in. The sphere is passed through the detector together with the product in order to observe whether a metal detection signal is issued.
- The testing schedule should state when the detector is to be tested and by whom. Example: The electrician on duty on a given shift has to test the detector using the testing object one hour after the start of each shift. The test results are recorded in the log book with the date, time and signature. Example: Test object recognised, 24 August 2007, 08.30, signed, Smith.

15.3. Notes

Normally, CASSEL commissions to adjust the metal detector to find the smallest metal pieces possible. Therefore please consider the following notes:

Keep the conveyor belt clean: Finger marks and shoe prints, visible or not, may contain metal particles.

Do not weld or grind near the detector or the conveyor without having covered the conveyor belt with e.g. cardboard. Sparks may burn into the surface of the conveyor and thus permanently contaminate the belt.

Do not change the conveyor belt construction without having asked the manufacturer of detector and belt.

16. Annex

16.1. Declarations



16.1.1. CE - Declaration of Conformity

The producer
CASSEL Messtechnik GmbH
In der Dehne 10
37127 Dransfeld, Germany

certifies herewith that the machines metal detector type METAL SHARK® 2 BD
are in conformity with the provisions of the following EC Directive(s) when installed in accordance with the
installation instructions contained in the product documentation:

- EG-Machinery Directive 2006/42/EC
- EC-Directive electromagnetic compatibility 2006/95/EC
- Electromagnetic Compatibility 2004/108/EC

The equipment complies with:

Safety:

EN ISO 12100-1	Safety of machinery - Basic concepts, general principles for design - Part 1: Basic terminology, methodology
EN ISO 12100-2	Safety of machinery - Basic concepts, general principles for design - Part 2: Technical principles
EN 60204-1	Safety of machinery - Electrical equipment of machines - Part 1: General requirements
EN 61010-1	Safety requirements for electrical equipment for measurement, control and laboratory use - Part 1: General requirements
EN 60529	Degrees of protection provided by enclosures (IP code)

Electromagnetic Compatibility (EMC) according to 61000-6-2/4:

EN 61000-3-3	Electromagnetic compatibility (EMC) - Part 3-3: Limits - Limitation of voltage changes, voltage fluctuations and flicker in public low-voltage supply systems, for equipment with rated current ≤ 16 A per phase and not subjected to conditional connection
EN 61000-4	Electromagnetic compatibility (EMC) - Part 4: Testing and measurement techniques
EN 61000-6-2	Electromagnetic compatibility (EMC) - Part 6-2: Generic standards - Immunity for industrial environments
EN 61000-6-4	Electromagnetic compatibility (EMC) - Part 6-4: Generic standards - Emission standard for industrial environments
EN 55011	Industrial scientific and medical (ISM) radio-frequency equipment - Electromagnetic disturbance characteristics - Limits and methods of measurement

Herewith we declare that we followed the relevant safety norms and requirements for technical safety and for explosion prevention for the intended use when constructing and producing this metal detector.

Structural changes which have effects on the technical information in this manual and on the intended utilisation, and therefore convert the machine considerably, make this declaration of conformity invalid!

Dransfeld, 27. October 2009
Cord Cassel, Managing Director

16.1.2. Declaration of Manufacturer

The producer
CASSEL Messtechnik GmbH
In der Dehne 10
37127 Dransfeld, Germany

certifies herewith that the machines metal detector type METAL SHARK® 2 BD are in conformity with the provisions of the following EC Directive(s) when installed in accordance with the installation instructions contained in the product documentation:

- EC-Machinery Directive 2006/42/EC
- EC-Directive electromagnetic compatibility 2006/95/EC
- Electromagnetic Compatibility 2004/108/EC

Herewith we declare that the described product is intended to be incorporated into machinery and must not be put into service until the machinery into which it is to be incorporated has been declared in conformity with the provisions of the EU-directives 2006/42/EC.

The equipment complies with:

Safety:

EN ISO 12100-1	Safety of machinery - Basic concepts, general principles for design - Part 1: Basic terminology, methodology
EN ISO 12100-2	Safety of machinery - Basic concepts, general principles for design - Part 2: Technical principles
EN 60204-1	Safety of machinery - Electrical equipment of machines - Part 1: General requirements
EN 61010-1	Safety requirements for electrical equipment for measurement, control and laboratory use - Part 1: General requirements
EN 60529	Degrees of protection provided by enclosures (IP code)

Electromagnetic Compatibility (EMC) according to 61000-6-2/4:

EN 61000-3-3	Electromagnetic compatibility (EMC) - Part 3-3: Limits - Limitation of voltage changes, voltage fluctuations and flicker in public low-voltage supply systems, for equipment with rated current ≤ 16 A per phase and not subjected to conditional connection
EN 61000-4	Electromagnetic compatibility (EMC) - Part 4: Testing and measurement techniques
EN 61000-6-2	Electromagnetic compatibility (EMC) - Part 6-2: Generic standards - Immunity for industrial environments
EN 61000-6-4	Electromagnetic compatibility (EMC) - Part 6-4: Generic standards - Emission standard for industrial environments
EN 55011	Industrial scientific and medical (ISM) radio-frequency equipment - Electromagnetic disturbance characteristics - Limits and methods of measurement

Herewith we declare that we followed the relevant safety norms and requirements for technical safety and for explosion prevention for the intended use when constructing and producing this metal detector.

Structural changes which have effects on the technical information in this manual and on the intended utilisation, and therefore convert the machine considerably, make this declaration of manufacturer invalid!



Dransfeld, 27. October 2009
Cord Cassel, Managing Director

Parameter List METAL SHARK® 2 BD/ Software Version 1.10a

Project: _____ Date: _____ Model: _____ Unit #: _____

✓ 1-3 = Required Password Level to enter this menu

Code	Name	Description	Read/ Write	Setting
REPORT MENU (✓ 1)				
A005	IFS/HACCP REPORT	Quality inspection report, printed to screen or printer	R	
A010	METAL REPORT	Shows report about last metal alerts	R	
A015	EVENT REPORT	Shows information about last events	R	
A020	METAL COUNTER	Increased by each metal detection	R	
A025	TOTAL COUNTER	Increased when product passes sensor	R	
A030	PRINT	Print mode	R/W	1 off 2 report 3 one by one 4 SharkDiag 5 SharkNet
A035	INTERFACE	Interface protocol	R/W	1 RS232 2 Ethernet
A040	BAUDRATE RS232	Speed of the interface	R/W	1 9600 2 14400 3 57600 4 115200 5 230400
A045	SHARKNET UNIT #	Number of the controller when in SHARKNET	R/W	
A050	MAIN SCREEN	Defines the main screen that is shown when metal detector is started	R/W	1 2D plot 2 bar graphs 3 scope
A055	HISTOGRAM LIMIT %	Only signals exceeding this threshold appear in histogram	R/W	
A060	INFO SOFTWARE	Shows software version	R	

Code	Name	Description	Read/ Write	Setting
TEST MENU (✓ 2)				
B005	AUTO PVS TEST	Performance Validation System Test	R/W	1 yes 2 no
B010	PVS FE mm	Size of FE-teststick to be used	R/W	
B015	PVS FE max %	Max signal, that is accepted as FE-teststick	R/W	
B020	PVS NonFE mm	Size of N-FE-teststick to be used	R/W	
B025	PVS NonFE max %	Max signal, that is accepted as N-FE-teststick	R/W	
B030	PVS SS mm	Size of SS-teststick to be used	R/W	
B035	PVS SS max %	Max signal, that is accepted as SS-teststick	R/W	
B040	PVS FREQ hrs	Time between two PVS tests	R/W	
B045	PVS WINDOW min	Max duration of PVS test	R/W	
B050	PVS ERROR COUNT	Max number of trials	R/W	
B055	PVS COUNT METAL	Teststick increases metal counter	R/W	1 yes 2 no
B060	PVS USE PRODUCT	PVS Test with product	R/W	1 yes 2 no

PASSWORD (MENU) (✓ 2)				
C005	OPEN LEVELS	No password protection up to this level	R/W	
C010	LEVEL 1 PASSWORD	Password for Level 1 user	R/W	
C015	LEVEL 2 PASSWORD	Password for Level 2 user	R/W	
C020	LEVEL 3 PASSWORD	Password for Level 3 user	R/W	
C025	LOGOUT	Logs out current user	R	

PRODUCT MENU (✓ 2)				
D005	PRODUCT NR.	Product number	R/W	
D010	PRODUCT NAME	Product name	R/W	
D015	PRODUCT IS...	Product characteristic (sets product adjusted settings)	R/W	1 dry 2 wet 3 salty 4 frozen 5 melting 6 alu foil 7 plastic 8 vibration 9 shock 10 neutral
D020	FREQ. SELECT	Selects frequency for product	R/W	
D025	TEACH MODE	Sets whether to teach quick or precise	R/W	1 quick 2 precise

Code	Name	Description	Read/ Write	Setting
PRODUCT MENU ► REJECT MENU (✓ 3)				
D035	DELAY mm	Reject delay in millimeter, calculated depending on SPEED	R/W	
D040	DURATION ms	Reject duration in milliseconds	R/W	
D045	METAL CONTACT	Programs the function of the metal alarm outputs	R/W	1 pulse 2 gf1 3 gf2 4 mesep 5 inline 6 hold 7 push1 8 push2 9 push3
D050	PUSHER TOL mm	Trigger tolerance for photo sensor	R/W	
D055	METAL-PHOTO mm	Distance metal detection – pusher's photo sensor	R/W	
D060	BELT STOP PUSH	Conveyor stops during rejection	R/W	1 yes 2 no

PRODUCT MENU ► TEACH SETUP (✓ 3)				
D065	SENSE MIN mV	Signals below this value are ignored (relat. to AMPLIFICATION X, Y = 100%)	R/W	
D070	TEACH SENSE mV	Sensitivity during teach (relating to AMPLIFICATION X, Y = 100%)	R/W	
D075	QUICK COUNT	Min number of products when teaching quick	R/W	
D080	PRECISE COUNT	Min number of products when teaching precise	R/W	
D085	TEACH TIME s	Duration of teach STEP1 and STEP2	R/W	
D090	TEACH EXTERN	Enables external product teach	R/W	1 yes 2 no
D095	TEACH REJECT	Enables rejection during teach	R/W	1 yes 2 no
D100	REMOTE PRODUCT	Activates remote product selection	R/W	1 yes 2 no
D105	AUTOMATIC TEACH	One product used for teach process (only possible with forwards/backwards belt control)	R/W	1 yes 2 no
D110	CONV. LENGTH mm	Conveyor length, for AUTOMATIC TEACH	R/W	
D115	AUTO FREQUENCY	Auto. frequency selection during teach	R/W	1 yes 2 no
D117	TEACH PHOTO mm	Distance from photo cell to sensor end	R/W	

PRODUCT MENU ► ADVANCED (✓ 3)				
D120	METAL SENSE mV	Metal detection above this threshold	R/W	
D125	PRODUCT X TOL.	Product compensation X (additionally to TOL X)	R/W	
D130	PRODUCT Y TOL.	Product compensation Y (additionally to TOL Y)	R/W	
D135	AMPLIFICATION X	Amplification X-channel (product signals)	R/W	
D140	AMPLIFICATION Y	Amplification Y-channel (metal signals)	R/W	
D145	ATTENUATION	Reduces sensor signal, e.g. at strong product effects	R/W	
D150	PHASE	Phase for product compensation	R/W	
D155	PHASE TRACK	Tracking steps when product phase drifts	R/W	

Code	Name	Description	Read/ Write	Setting
SYSTEM MENU (✓ 3)				
E005	SPEED mm/s	Speed of product through sensor. IMPORTANT – Must match with real speed.	R/W	
E010	LANGUAGE	Sets language	R/W	
SYSTEM MENU ► DATE/TIME MENU (✓ 3)				
E015	SET DATE	Date used in all reports	R/W	
E020	SET TIME	Time used in all reports	R/W	
SYSTEM MENU ► AUTOSPEED MENU (✓ 3)				
E025	AUTOSPEED	Activates autospeed (only belts with frequency inverter)	R/W	1 yes 2 no
E030	BELT STOP mV	Calibrates belt speed (Terminal 3, AIN2) at 0 mm/sec	R/W	
E035	CAL SPEED mm/s	Enter calibrated belt speed	R/W	
E040	CAL SPEED mV	Calibrates belt speed (Terminal 3, AIN2) of set belt speed	R/W	
E005	SPEED mm/s	Speed of product through sensor. IMPORTANT – Must match with real speed.	R	
SYSTEM MENU ► CIP MENU (✓ 3)				
E045	CIP Reject s	Clean in place: reject open timing (seconds)	R/W	
E050	CIP Normal s	Clean in place: timing for normal position	R/W	
E055	CIP Timeout min	Clean in place: reject normal timing (seconds)	R/W	
SYSTEM MENU ► BRC MENU (✓ 3)				
E060	REJECT CONFIRM	Checks if product was rejected (photo sensor needed)	R/W	1 yes 2 no
E065	BIN FULL	Checks if bin is full (photo sensor required)	R/W	1 yes 2 no
E070	LOW AIR	Checks if enough air pressure (air jet required)	R/W	1 yes 2 no

Code	Name	Description	Read/Write	Setting
SYSTEM MENU ► IN/OUT MENU (✓ 3)				
		input off met/err reset conveyor on/off start teach reject test reject valid reject sync reject safety keypad lock low air start cip bin full met count reset false trip product 120 met/err key booster ok belt splice product LS test no reject		
E080	INPUT LINE 1			
E085	INPUT LINE 2			
E090	INPUT LINE 3			
E095	INPUT LINE 4			
E100	INPUT LINE 5			
E105	INPUT LINE 6			
E110	INPUT LINE 7			
E115	INPUT LINE 8			
		output off metal metal inverse error error inverse met+err met+err inv. metal zero del pv test dual freq teach confirm cip out start conveyor pusher conv. forward conv. reverse big metal booster on metal clocked metal CW error CW		
E120	OUTPUT LINE 1			
E125	OUTPUT LINE 2			
E130	OUTPUT LINE 3			
E135	OUTPUT LINE 4			
E140	OUTPUT LINE 5			
E145	OUTPUT LINE 6			
E150	OUTPUT LINE 7			
E155	OUTPUT LINE 8			

SYSTEM MENU ► FILTER MENU (✓ 3)				
E160	VIBRATION mV	makes VIBRATION FILTER stronger (increase mV) or weaker (decrease mV)	R/W	
E165	VIBRATION FILTER	Avoids false trips if sensor is subjected to vibrations	R/W	1 yes 2 no
E170	BP FILTER	Shall always be CCF, unless specified other by Cassel CAS-SEL	R/W	1 no filter 2 FFT 3 CCF
E175	LP FILTER	Avoids false trips from VFDs and similar noise sources	R/W	1 yes 2 no
E180	GF MODE	Enables superfast metal detection for gravity feed	R/W	1 yes 2 no

Code	Nom	Description	Lecture/ Ecriture	Réglage
------	-----	-------------	----------------------	---------

MENU USINE (✓ 3)

MENU USINE ► SENSOR CALIB. (✓ 3, NEVER CHANGE!)				
F005	SENSOR FIELD mm	Dimensions du capteur	R/W	
F010	BALANCE FACTOR	Facteur régulation balance du capteur	R/W	
F015	FREQUENCY 1[Hz]	Frequence résonance capteur	R/W	
F020	PHASE 1 CALIB.	Phase zéro calibration capteur	R/W	
F025	FREQUENCY 2[Hz]	Frequence résonance capteur	R/W	
F035	PHASE 2 CALIB.	Phase zéro calibration capteur	R/W	
F040	FREQUENCY 3[Hz]	Frequence résonance capteur	R/W	
F045	PHASE 3 CALIB.	Phase zéro calibration capteur	R/W	
F050	FREQUENCY 4[Hz]	Frequence résonance capteur	R/W	
F055	PHASE 4 CALIB.	Phase zéro calibration capteur	R/W	
F060	FF BOARD REV.	Choisit écran principal pour capteur multifréquence	R/W	
F065	mV CALIBR.	mV calibration factor 0.01 - 1.99. standard = 1.00	R/W	

About CASSEL Messtechnik GmbH

As a manufacturer CASSEL is committed to highest quality standards. For more than ten years our goal has been to ensure the quality of your products. We have earned our reputation by protecting yours.

We supply customers in different industries worldwide such as Foods, Plastics, Pharmaceuticals, Textile, Timber and Mining.

Our headquarters and state of the art manufacturing facility are located near Hanover in the heart of Germany. Each year we manufacture and deliver over 1000 metal detection systems.

Approximately 80% of the production is heading for export markets. We have a worldwide network of partners and representations. This way we ensure that you get the very best service and support no matter where you use one of our metal detectors.

Contact

CASSEL North America

9 - 18812 96Ave
Surrey BC, Canada V4N 3R1
Tel: +1 604 607-6028
Fax: +1 604 607-6026
E-Mail: service@metal-shark.com
Web: www.metal-shark.com



About this manual

Original Manual / Documentation for Metal Detector METAL SHARK® 2 BD

Updated: 28, October 2009